

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD
190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853
ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2200098

Date: 06 Apr 2022

Veh Reg No: SKS3910Z

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3606030417

Reg. Date: 13/04/2015

Your Ref No: SGU2115X

Claim Type: Third Party

Accident Date: 05/04/2022

TP Veh Reg No: SGU2115X

Estimate Repair Cost to Vehicle No :SKS3910Z

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC REAR BUMPER <i>Rehnd</i>	452.80 ✓	
2	1 PC REAR BUMPER REINFORCEMENT <i>But</i>	316.60 ✓	
3	1 PC REAR BUMPER SIDE RETAINER RH <i>Dmg</i>	113.90 ✓	
4	1 PC REAR BUMPER RETAINER (SMALL) LH <i>Ken</i>	31.20 ✓	
5	1 PC REAR BUMPER MUDFLAP RH <i>Ken</i>	56.90 ✗	
6	1 PC REAR BUMPER REFLECTOR - RH <i>Rehnd.</i>	179.80 ✓	
7	1 PC REAR PANEL <i>But</i>	620.20 ✗	
8	1 PC REAR PANEL TRIM <i>Ken</i>	232.20 ✗	
9	1 PC TAIL LAMP - RH <i>Crashd</i>	397.50 ✓	
10	1 PC REAR FENDER INNER TRIM RH <i>Ken</i>	355.90 ✗	
11	1 PC BOOT LID RUBBER <i>Ken</i>	166.40 ✗	
		2,923.40	
	Less 25%	730.85	2,192.57
Special Net			
12	1 SET REAR BUMPER STICKER <i>Ken</i>	280.00 250	
13	1 SET REAR BUMPER MUDFLAP CLIPS RH <i>Ken</i>	30.00 ✗	
14	1 SET REAR BUMPER CLIPS <i>Ken</i>	40.00 ✓	
15	2 PCS "L" PLATE BRACKET <i>Ken</i>	80.00 60	
16	1 SET REAR PANEL TRIM CLIPS <i>Ken</i>	40.00 ✗	
17	1 SET REAR FENDER INNER TRIM CLIPS <i>Ken</i>	60.00 ✗	
18	1 PC REAR FENDER STICKER RH <i>Ken</i>	290.00 220	
		820.00	820.00
Labour			
19	1 TO CHECK WIRING	50.00 30	
20	1 TO REPLACE STICKERS	80.00 60	
21	1 TO REMOVE AND REFIT REAR INNER TRIM	80.00 ✗	
22	1 TO SPRAY UNDERSEAL	80.00 40	
23	1 (REAR) TO SPRAY PAINTING	900.00 700	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AUTO & GENERAL INSURANCE (S) PTE LTD

190 CLEMENCEAU AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

TEL: 6221 2199 FAX: 6725 0853

ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST2200098

Date: 06 Apr 2022

Veh Reg No: SKS3910Z

Make/Model: TOYOTA
VIOSJGRADEMT

Chasis No: MHFBT9F3606030417

Reg. Date: 13/04/2015

Your Ref No: SGU2115X

Claim Type: Third Party

Accident Date: 05/04/2022

TP Veh Reg No: SGU2115X

Estimate Repair Cost to Vehicle No :SKS3910Z

Quantity	Description	List Price	Amount
		SS	SS
24	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	900.00 400.	
	930	2,090.00	2,090.00
		Total	S\$ 5,102.57
		Add GST @ 7%	357.18
		Total Amount Payable	S\$ 5,459.75

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED FIFTY NINE AND CENTS SEVENTY FIVE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
H/S 07/04/22
OSR

total: 2818.50

H/S: 2K1K

2-1K