

-FCI D.O.H. : 29/3/2022
-Survey by Tarfikh on 9/5/2022

-Veron



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBL4418R Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 685.60 X NN
2	1	Front bumper left bracket	\$ 98.80 X NN
3	1	Front bumper side cover	\$ 69.80 X NN
4	1	Front bumper reinforcement	\$ 485.00 X NN
5	1	Bonnet /front panel	\$ 1,082.50 BUC 856
6	1	Bonnet lock	\$ 159.80 BT 96
7	2	Front panel both side square rubber mounting	\$ 79.60 X NN
8	1	Bonnet emblem	\$ 95.00 NEC 73.50
9	1	Front grille assy base	\$ 530.00 CRA 3582
10	1	Front grille cover	\$ 225.00 CUT
11	1	Front grille chrome moulding	\$ 225.00 X NN
12	1	Front bonnet hinges	\$ 85.00 X NN
13	1	Front bonnet rubber	\$ 95.00 X SVC
14	1	lower support metal	\$ 225.00 X R
15	1	Front left headlamp	\$ 695.00 CRA
16	1	Front left headlamp bracket	\$ 85.60 X NN
17	1	Front right headlamp	\$ 695.00 X NN
18	1	Front radiator frame -	\$ 597.10 X NN
19	1	Side mirror assy w	\$ 1,372.30 X NC (CUT)
20	1	Side mirror trim	\$ 150.00 X NC (CUT)
21	1	Wiper link	\$ 294.50 X NN
22	1	Wiper motor	\$ 895.00 X NN
23	✓ 1	Coolant tank	\$ 658.10 DD 206
24	1	Step	\$ 271.90 X NC (CUT)
25	1	Front panel rubber seal -	\$ 225.00 X NN
26	1	Inter cooler cover squzzed	\$ 179.80 X NN
27	1	Inter cooler assy	\$ 1,980.60 X NN
28	1	Condenser	\$ 2,066.80 X NN
		Parts sub-total	\$ 14,532.80



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBL4418R Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	--------------------------

Special Nett Items

1	10	Front bumper clips	\$ 60.00	} 30 nec
2	6	Front bumper lower grille clips	\$ 80.00	
3	8	Front bonnet inner board clips	\$ 60.00	} 30 NEC
4	6	Front grille chrome moulding clips	\$ 50.00	
5	6	Front grille clips	\$ 50.00	} 30 NEC
6	6	Front top panel clips	\$ 80.00	
8	10	Front left door inner board clips	\$ 80.00	X NC (NEC)
9	8	Front support panel top garnish clips	\$ 60.00	
10	1	Front no plate with cashing	\$ 80.00	X NN
13	1	Car body sticker	\$ 50.00	
15	1	Glass sealant	\$ 45.00	X NN
16	1	Strength sealant	\$ 45.00	
17	1	Coolant original Toyota	\$ 90.00	X NN
Special Nett Items			\$ 830.00	



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

GBL4418R Toyota Hiace

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 2,000.00	400 500
2	To putty and spray painting front portion.	\$ 1,800.00	500 600
3	To check wiring and focus front headlamp.	\$ 60.00	30
4	To apply anti rust proofing to front affected area.	\$ 150.00	30
5	To remove and install front undercarriage parts.	\$ 120.00	X
6	To balance front right wheel.	\$ 60.00	X
7	To conduct wheel alignment.	\$ 120.00	X
8	To remove and install front bonnet lock mechanism assy.	\$ 60.00	X
9	To remove and install condensor, innner cooler and check airocn system, top up gas, check leakage	\$ 250.00	X
10	To remove the dismantle the door, door rubber and door seal and window seal, as to need welding the door arch /car body area	\$ 200.00	X
11	To remove the front windscreen to assist the repair	\$ 150.00	X
12	To remvoe the door sticker and replace the new	\$ 60.00	X

Total labour : \$ 5,030.00

4 days 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2016.80

20392.80