

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 1831R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,023.10	1,023.10
1	RETAINER LH FRT	NECESSARY	15.50	15.50
1	BRACKET LH FRT	NOT NECESSARY	28.00	-
1	COVER FOG LAMP NO.1	SCRATCHED	16.40	16.40
1	COVER FOG LAMP NO.2	SCRATCHED	19.60	19.60
1	STIFF 'A' FRT	NOT NECESSARY	115.50	-
10	NUT, CLIP	NOT NECESSARY	37.00	-
5	FASTENER	NECESSARY	15.00	15.00
1	RETAINER S.S ULTRASONIC SIDE	NECESSARY	18.20	18.20
1	SENSOR ULTRASONIC SIDE	NOT NECESSARY	203.60	-
1	FRONT FENDER LH	BENT	380.10	380.10
1	STAY FENDER LH	NECESSARY	51.30	51.30
1	WHEEL ARCH FENDER FRT	SCRATCHED	158.30	158.30
1	MUD GUARD LH FRT	NOT NECESSARY	98.20	-
10	FASTENER	NOT NECESSARY	30.00	-
1	HEADLAMP LH	SCRATCHED	3,562.70	3,562.70
1	FASTENER	NECESSARY	3.50	3.50
1	MOULD CHROME FRONT LH	SCRATCHED	152.80	152.80
1	CLIP	NECESSARY	13.70	13.70
1	BRACKET FOG LAMP LH	NOT NECESSARY	18.90	-
1	FOG LAMP LH	NOT NECESSARY	663.60	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			6,675.00	5,450.20
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR FRONT DOOR LH.		2,640.00	1,320.00
	TO RESPRAY FRONT BUMPER, FRONT FENDER LH AND FRONT DOOR LH.		2,520.00	1,890.00
	TO TRANSFER FRONT PEDESTRIAN SENSORS.		660.00	330.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCRIONING.		250.00	180.00

Report Ref No. CS/FCI22003239/Rty3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		300.00	220.00
			6,370.00	3,940.00
	GRAND TOTAL		13,045.00	9,390.20
	RECOMMENDED COST OF REPAIRS			9 390 20

Report Ref No. CS/FCI22003239/Rty3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.