



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22003239/Rty3s2	
			Date: 24/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJP 6711P	Veh. Inspected	SMH 1831R
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22001015MFQC	Excess (\$)	0.00
	Assign From	VICALPEH	Assign Date	07/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA CX-5 2.0 AT	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JM6KF2W7AK0245566	Colour	BROWN
	Odometer	27649 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/65 R17	YOKOHAMA	6 mm
	L/H Front Tyre	255/65 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	255/65 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	255/65 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/04/2022	Inspection Date	08/04/2022
	Survey held at	27A TANJONG PENJURU		
	Repairer	TRANS EUOKARS PTE LTD		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	