




ASS. REC.
Henne

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029129
Tang Sow Boon

Page 1 of 3
Your ref. TP-XE 853U Allianz
Job No 72564
Our ref. 22.04.03
Payment
Date 6/4/2022

Attn

Vehicle No SLN 7701Z
Vehicle Model : Toyota Altis
Accident on ... 2/4/2022

Not Authorized
U/Sing & 770odr
Recovery B4pain
10 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front fender RH 737.50	737.50	25.00	553.13
1.00	Pc	Front fender Dual VVT-i emblem RH	39.43	25.00	29.57
6.00	Pcs	Front fender inner shield clips RH - 1	3.00	25.00	13.50
3.00	Pcs	Front fender inner shield clips RH - 2	3.50	25.00	7.88
1.00	Pc	Front sport rim RH (17")	2,190.40	25.00	1,642.80
1.00	Pc	Front door RH 1079.60	1,079.60	25.00	809.70
1.00	Pc	Front door outer handle RH	155.20	25.00	116.40
1.00	Pc	Front door outer lock cover RH	69.20	25.00	51.90
1.00	Set	Front door black tape RH	67.50	25.00	50.63
1.00	Pc	Front door lower hinge RH	87.20	25.00	65.40
1.00	Pc	Front shock absorber RH 425.80	425.80	25.00	319.35
1.00	Pc	Front shock absorber top mounting RH	169.82	25.00	127.37
1.00	Pc	Front knuckle arm RH	441.42	25.00	331.07
1.00	Pc	Front knuckle bearing RH	119.43	25.00	89.57
1.00	Pc	Front steering rack 1524.90	1,524.90	25.00	1,143.68
1.00	Pc	Rear door RH 1069.20	1,069.20	25.00	801.90
1.00	Pc	Rear door lower hinge RH	81.63	25.00	61.22
1.00	Set	Rear door black tape RH	67.50	25.00	50.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

公司拥有最先进的 CAROLINER MARK IV 机械，还有先进的 SAICO Deluxe 喷漆烘炉。 services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles.

DRIVER
Name of Driver
Accident report SC1Q224K0003

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UBN: 199407592C

ESTIMATE

EST. No EST0029129
Tang Sow Boon

Page 2 of 3
Your ref. TP-XE 853U Allianz
Job No. 72564
Our ref. 22.04.03
Payment
Date 6/4/2022

Attn

Vehicle No SLN 7701Z
Vehicle Model Toyota Altis
Accident on 2/4/2022

Quantity	Unit	Description	Unit price	Disc. pot.	Amount
1.00	Pc	Rear sport rim RH (17")	2,190.40	25.00	1,642.80
		Labour & Misc:			
1.00		Towing fee (King Dolly)	130.00		130.00
1.00		To check wheel alignment	80.00		80.00
1.00		To dismantle + refix front axle	120.00		120.00
1.00		To dismantle + renew front undercarriage RH	240.00		240.00
1.00		To renew front and rear sport rim RH and wheel balancing	60.00		60.00
1.00		To transfer sun visor + supply 3M tape	60.00		60.00
1.00		To knock dents on rear fender RH, rear door pillar RH and renew of parts	1,200.00		1,200.00

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。外，还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support lly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO luxue oven heater for re-spraying all motor vehicles."

CIF

7,059.60

DRIVER

Driver

224K0003

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029129
Tang Sow Boon

Page 3 of 3
Your ref. TP-XE 853U Allianz
Job No. 72564
Our ref. 22.04.03
Payment
Date 6/4/2022

Attn

Vehicle No SLN 7701Z
Vehicle Model : Toyota Altis
Accident on ... 2/4/2022

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00		To spray paint (including rear bumper, blend to roof panel)	1,500.00		1,500.00

1300h

12,407.98

Sub-Total 11,298.50
GST 7.00% 790.90
Total S\$ 12,089.40

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。

还有先进的 SAICO Deluxe 喷漆烘炉。

services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."

C/F

7,059.60