

ASS. REC. BY:

REF:

A15/22003241/kv

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured: XE 853U

Policy No.

Claims No. MLPAISCL2022-00040FR

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 77012 Yr Regn: 05, 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy HTIS c.c. 1598

Colour:

m Black A/C: Insured / Std / NI / NA

Sp. Reading

172003 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053R EH10455910P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/45 ZR17

R: Petlas

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

R/Bal.

P

mm

Rear

R/Bal.

9

mm

L/Bal.

P

mm

L/Bal.

9

mm

D.O.A.

2/4/22

D.O.I.

8/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s body &amp; u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/5/22

Kenneth informed LS \$7700 (Red 4707.98, 37%)

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: 10

☐

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

12/5/22-typist

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Report Format: Merimen

mp Sum / t.B.: (\$ 7700

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0029129  
Tang Sow Boon

Page ..... 1 of 3  
Your ref. .... TP-XE 853U Allianz  
Job No. .... 72564  
Our ref. .... 22.04.03  
Payment .....  
Date ..... 6/4/2022

Attn .....

Vehicle No .... SLN 7701Z  
Vehicle Model : Toyota Altis  
Accident on ... 2/4/2022

*Not Authorised*  
*U/Sing &*  
*Anthony Bepain*  
*10 days*

| Quantity         | Unit | Description                            | Unit price | Disc. pot. | Amount   |   |
|------------------|------|----------------------------------------|------------|------------|----------|---|
| Supply of Parts: |      |                                        |            |            |          |   |
| 1.00             | Pc   | Front fender RH                        | 737.50     | 25.00      | 553.13   | ✓ |
| 1.00             | Pc   | Front fender Dual VVT-i emblem RH      | 39.43      | 25.00      | 29.57    | ✓ |
| 6.00             | Pcs  | Front fender inner shield clips RH - 1 | 3.00       | 25.00      | 13.50    | ✓ |
| 3.00             | Pcs  | Front fender inner shield clips RH - 2 | 3.50       | 25.00      | 7.88     | ✓ |
| 1.00             | Pc   | Front sport rim RH (17")               | 2,190.40   | 25.00      | 1,642.80 | X |
| 1.00             | Pc   | Front door RH                          | 1,079.60   | 25.00      | 809.70   | ✓ |
| 1.00             | Pc   | Front door outer handle RH             | 155.20     | 25.00      | 116.40   | ✓ |
| 1.00             | Pc   | Front door outer lock cover RH         | 69.20      | 25.00      | 51.90    | ✓ |
| 1.00             | Set  | Front door black tape RH               | 67.50      | 25.00      | 50.63    | ✓ |
| 1.00             | Pc   | Front door lower hinge RH              | 87.20      | 25.00      | 65.40    | X |
| 1.00             | Pc   | Front shock absorber RH                | 425.80     | 25.00      | 319.35   | 7 |
| 1.00             | Pc   | Front shock absorber top mounting RH   | 169.82     | 25.00      | 127.37   | X |
| 1.00             | Pc   | Front knuckle arm RH                   | 441.42     | 25.00      | 331.07   | 7 |
| 1.00             | Pc   | Front knuckle bearing RH               | 119.43     | 25.00      | 89.57    | 7 |
| 1.00             | Pc   | Front steering rack                    | 1,524.90   | 25.00      | 1,143.68 | 2 |
| 1.00             | Pc   | Rear door RH                           | 1,069.20   | 25.00      | 801.90   | ✓ |
| 1.00             | Pc   | Rear door lower hinge RH               | 81.63      | 25.00      | 61.22    | ✓ |
| 1.00             | Set  | Rear door black tape RH                | 67.50      | 25.00      | 50.63    | ✓ |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

公司拥有最先进的 CAROLINER MARK IV 机械, 可供给各种款式的车身及给予快速与准确的测量方式和大铁修理。  
外, 还有先进的 SAICO Deluxe 喷漆烘炉。  
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support  
olly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO  
deluxe oven heater for re-spraying all motor vehicles."

Acknowledged by Repairer

Signature:

Date:

# 來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No .....: EST0029129  
Tang Sow Boon

Page .....: 2 of 3  
Your ref. ....: TP-XE 853U Allianz  
Job No. ....: 72564  
Our ref. ....: 22.04.03  
Payment .....  
Date .....: 6/4/2022

Attn .....

Vehicle No ....: SLN 7701Z  
Vehicle Model : Toyota Altis  
Accident on ...: 2/4/2022

| Quantity | Unit | Description                                                              | Unit price          | Disc. pct. | Amount               |
|----------|------|--------------------------------------------------------------------------|---------------------|------------|----------------------|
| 1.00     | Pc   | Rear sport rim RH (17")                                                  | <i>Net</i> 2,190.40 | 25.00      | 1,642.80 ✓           |
|          |      | Labour & Misc:                                                           |                     |            |                      |
| 1.00     |      | Towing fee (King Dolly)                                                  | 130.00              |            | <i>Bill</i> 130.00 ? |
| 1.00     |      | To check wheel alignment                                                 | 80.00               |            | 80.00 <i>60</i>      |
| 1.00     |      | To dismantle + refix front axle                                          | 120.00              |            | 120.00 ?             |
| 1.00     |      | To dismantle + renew front undercarriage RH                              | 240.00              |            | 240.00 ?             |
| 1.00     |      | To renew front and rear sport rim RH and wheel balancing                 | 60.00               |            | 60.00 <i>20</i>      |
| 1.00     |      | To transfer sun visor + supply 3M tape                                   | 60.00               |            | <i>Net</i> 60.00 ✓   |
| 1.00     |      | To knock dents on rear fender RH, rear door pillar RH and renew of parts | 1,200.00            |            | 1,200.00 <i>1100</i> |

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0029129  
Tang Sow Boon

Page ..... 3 of 3  
Your ref. .... TP-XE 853U Allianz  
Job No. .... 72564  
Our ref. .... 22.04.03  
Payment .....  
Date ..... 6/4/2022

Attn .....

Vehicle No .... SLN 7701Z  
Vehicle Model : Toyota Altis  
Accident on ... 2/4/2022

| Quantity | Unit | Description                                                 | Unit price | Disc. pct. | Amount   |
|----------|------|-------------------------------------------------------------|------------|------------|----------|
| 1.00     |      | To spray paint (including rear bumper, blend to roof panel) | 1,500.00   |            | 1,500.00 |

1300h

☐ Prel. Report  
☐ Final Report

Add Fee: ☐  
Sub-Total 11,298.50  
GST 7.00% 790.90  
Total S\$ 12,089.40

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。  
外，还有先进的 SAICO Deluxe 喷漆烘炉。  
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support  
olly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO  
eluxe oven heater for re-spraying all motor vehicles."