

ASS. REC. BY:

REF:

A15/22003241/kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 77012 Yr Regn: 05, 17

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy HTIS c.c. 1598

Colour:

m Black A/C: Insured / Std / NI / NA

Sp. Reading

172003 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053R EH 10-455910P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215/45 ZR17

R: Petlas

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

R/Bal.

P

mm

Rear

R/Bal.

9

mm

L/Bal.

P

mm

L/Bal.

9

mm

D.O.A.

2/4/22

D.O.I.

8/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

o/s body & u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

Date/Time, File Return to?

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Transportation:

S + RS. SI

Photos

Others

Report Format :

mp Sum / I.B.I: (\$

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029129
Tang Sow Boon

Page 1 of 3
Your ref. TP-XE 853U Allianz
Job No. 72564
Our ref. 22.04.03
Payment
Date 6/4/2022

Attn

Vehicle No SLN 7701Z
Vehicle Model : Toyota Altis
Accident on ... 2/4/2022

Not Authorised
U/Sing &
Anthony Bepain
10 days

Quantity	Unit	Description	Unit price	Disc. pot.	Amount	
Supply of Parts:						
1.00	Pc	Front fender RH	737.50	25.00	553.13	✓
1.00	Pc	Front fender Dual VVT-i emblem RH	39.43	25.00	29.57	✓
6.00	Pcs	Front fender inner shield clips RH - 1	3.00	25.00	13.50	✓
3.00	Pcs	Front fender inner shield clips RH - 2	3.50	25.00	7.88	✓
1.00	Pc	Front sport rim RH (17")	2,190.40	25.00	1,642.80	X
1.00	Pc	Front door RH	1,079.60	25.00	809.70	✓
1.00	Pc	Front door outer handle RH	155.20	25.00	116.40	✓
1.00	Pc	Front door outer lock cover RH	69.20	25.00	51.90	✓
1.00	Set	Front door black tape RH	67.50	25.00	50.63	✓
1.00	Pc	Front door lower hinge RH	87.20	25.00	65.40	X
1.00	Pc	Front shock absorber RH	425.80	25.00	319.35	7
1.00	Pc	Front shock absorber top mounting RH	169.82	25.00	127.37	X
1.00	Pc	Front knuckle arm RH	441.42	25.00	331.07	7
1.00	Pc	Front knuckle bearing RH	119.43	25.00	89.57	7
1.00	Pc	Front steering rack	1,524.90	25.00	1,143.68	2
1.00	Pc	Rear door RH	1,069.20	25.00	801.90	✓
1.00	Pc	Rear door lower hinge RH	81.63	25.00	61.22	✓
1.00	Set	Rear door black tape RH	67.50	25.00	50.63	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

公司拥有最先进的 CAROLINER MARK IV 机械, 可供给各种款式的车身及给予快速与准确的测量方式和大铁修理。
外, 还有先进的 SAICO Deluxe 喷漆烘炉。
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
olly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
deluxe oven heater for re-spraying all motor vehicles."

Acknowledged by Repairer

Signature:

Date:

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029129
Tang Sow Boon

Page 2 of 3
Your ref. TP-XE 853U Allianz
Job No. 72564
Our ref. 22.04.03
Payment
Date 6/4/2022

Attn

Vehicle No SLN 7701Z
Vehicle Model : Toyota Altis
Accident on ... 2/4/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00	Pc	Rear sport rim RH (17")	<i>Net</i> 2,190.40	25.00	1,642.80	✓
		Labour & Misc:				
1.00		Towing fee (King Dolly)	130.00		<i>Bill</i> 130.00	?
1.00		To check wheel alignment	80.00		80.00	<i>60</i>
1.00		To dismantle + refix front axle	120.00		120.00	?
1.00		To dismantle + renew front undercarriage RH	240.00		240.00	?
1.00		To renew front and rear sport rim RH and wheel balancing	60.00		60.00	<i>20</i>
1.00		To transfer sun visor + supply 3M tape	60.00		<i>Net</i> 60.00	✓
1.00		To knock dents on rear fender RH, rear door pillar RH and renew of parts	1,200.00		1,200.00	<i>1100</i>

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0029129
Tang Sow Boon

Page 3 of 3
Your ref. TP-XE 853U Allianz
Job No. 72564
Our ref. 22.04.03
Payment
Date 6/4/2022

Attn
Vehicle No SLN 7701Z
Vehicle Model : Toyota Altis
Accident on ... 2/4/2022

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To spray paint (including rear bumper, blend to roof panel)	1,500.00		1,500.00

1300h

☐ Prel. Report
☐ Final Report

Sub-Total 11,298.50
GST 7.00% 790.90
Total S\$ 12,089.40

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
外，还有先进的 SAICO Deluxe 喷漆烘炉。
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
olly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
eluxe oven heater for re-spraying all motor vehicles."