

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

SHD33P

AAD2204-

Not Notified
for
repairing & painting
11 Bmp & 7400ph

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

08 APR 2022**SHD33P**

WDD2120012B221137

200303878K

MERCEDES BENZ

E 220 BLUETEC

06/04/2022

SLL8786H/ Auto & General

16/12/2015

PART		LIST	
1	Front Bumper 1417.44	\$	Bu 1,417.44 ✓
1	Front Bumper Reinforcement 569.72	\$	Bu 569.72 ✓
1	Radiator Grille	\$	CM 814.17 ✓
1	Front Bumper Lower Grille Carrier	\$	su 125.10 X
1	Front Bumper Inner Sponge Absorber	\$	CM 147.37 ✓
1	Front Bumper Side Support Bracket	\$	n 57.83 X
1	Front Bumper Reinforcement Bracket	\$	n 305.34 X
1	Front Bumper Fog Lamp Grille LH	\$	su 50.70 X
1	Front Bonnet	\$	Bu 2,473.44 ✓
1	Bonnet Hinge LH	\$	n 157.03 X
1	Bonnet Hinge RH	\$	n 157.03 X
1	Front Headlamp LH	\$	CM 3,501.15 ✓
1	Headlamp Control Unit 3501.15	\$	su 1,013.59 X
1	Front Headlamp Panel LH	\$	n 275.80 X
TOTAL		\$	11,065.71
10%		\$	1,106.57
		\$	9,959.14

Special Nett

1SET FRONT BUMPER CLIP	\$	Bu 100.00 601a
1SET Front Bumper Inner Frame Clip LH	\$	na 90.00 X
1SET Front Bumper Inner Frame Metal Clip LH	\$	na 60.00 X
1 Front Bumper Center Air Grille Clip	\$	na 70.00 X
1 Front Bumper Retainer Clip	\$	na 80.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Singapore 569111

Co./GST Reg. No. 201019626G

Tel No. : 6287 6666 Fax No. : 6257 1330

AAD2204-

SHD33P

1	Front Bumper Rivet	\$	<i>nn</i> 90.00	✓
1	Front Bumper Fog Lamp Grille Clip	\$	<i>nn</i> 65.00	X
TOTAL		\$	555.00	

GRAND TOTAL \$ 10,514.14**LABOUR**

To Transfer Of Bumper Fittings, Attachment And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	8,500.00	<i>500</i>
Putty And Spray Painting Of The Affected Portion.	\$	8,500.00	<i>500</i>
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	<i>nn</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>30</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20</i>
To Transfer Of Bootlid Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
To rust-proofing of the affected areas.	\$	<i>Repair</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
TOTAL	\$	18,830.00	