



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M0359J

Date: 04<sup>th</sup> May 2022

Our Ref: CS3/ASM21002655/Gvy3e2-1

**M/s Axa Insurance Pte Ltd**

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FX 898D  
INSURED VEHICLE: SHC 3998R  
ACCIDENT DATE: 13/02/2021**

We thank you for your instruction on 07/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FX 898D from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles FX 898D and SHC 3998R.
- c) Final Repair Bill of FX 898D from M/s Equator Brotherhood.
- d) Colour damaged vehicle photographs of FX 898D.

Pre-Repair Inspection Date : 26/02/2021 at M/s Equator Brotherhood, 25 Kaki Bukit Road 4 #03-19 Synergy@KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FX 898D
Make & Model	: Honda Phantom
Year of Registration	: 2003
Chassis Number	: TA2000018113
Engine Capacity	: 197 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.