

# COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

SAS-KIV

LKK-

DATE: 06.04.22

INSURANCE: NTUC CL(S)

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHD4338J

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 481.10
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Moulding	1		\$ 368.50
	Radiator Grille	1		\$ 1,409.10
	Headlamp RH	1		\$ 2,110.30
	DayLight RH	1		\$ 642.50
	DayLight Grille RH	1		\$ 93.45
	<b>SUB TOTAL</b>			\$ 5,126.95
	<b>LESS 20%</b>			\$ 1,025.39
	<b>TOTAL SPARE PARTS</b>			\$ 4,101.56
	<u>Labour Charge</u>			
	Panel Beating			\$ 400.00
	Spray Painting			\$ 300.00
	Check Wirings			\$ 40.00
	<b>TOTAL LABOUR</b>			\$ 740.00
	<b>ESTIMATE TOTAL</b>			\$ 4,841.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thovan  
 92235769  
 6/4/22 #1615  
 LIS repair 2 days w/p

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: