

Item: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4193347

JC NO305511560


MEMBER COMFORT TRANSPORTATION PTE LTD MEMBER NO. 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) UNIT CARD NO.	REGN NO: SHD4338J	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G3)	DATE/TIME IN 06.04.2022 13:55
	YR OF MANU. 07.11.2019	TARGET DATE
	CHASSIS CODE KMHC851CVLU188276	COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 06.04.2022
 DURE: 3P 06.04.2022

NO \ LABOR CODE
 0010 PB

DESCRIPTION
PANEL BEATING-SHD4338J-TP



& PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ment Slip

Exit Pass

SHD4338J

LIMITS

Vehicle No.:

SHD4338J

Service Advisor

Signature/Date

Name of Service Advisor

Date

to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

SAS-KIV

LKK-

DATE: 06.04.22

INSURANCE: NTUC (LIS)

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO: SHD4338J

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 481.10
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Upper Moulding	1		\$ 368.50
	Radiator Grille	1		\$ 1,409.10
	Headlamp RH	1		\$ 2,110.30
	DayLight RH	1		\$ 642.50
	DayLight Grille RH	1		\$ 93.45
	SUB TOTAL			\$ 5,126.95
	LESS 20%			\$ 1,025.39
	TOTAL SPARE PARTS			\$ 4,101.56
	Labour Charge			\$ 400.00
	Panel Beating			\$ 300.00
	Spray Painting			\$ 40.00
	Check Wirings			
	TOTAL LABOUR			\$ 740.00
	ESTIMATE TOTAL			\$ 4,841.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan
 92235761
 6/4/22 from 1/6/22
 LIS repair 2 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: