



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg (199806235M)

Vehicle No. YN2564G MITSUBISHI CANTER FE83BEOSRDEA

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front door LH/RH @2*\$2038 LH-bt / RH-repair		4076	2038
2	Front door trim board LH/RH @2*\$638 de		1276	
1	Front bumper bt		986	
1	Center grille ca		599	
1	Center grille logo badge		85	
1	Center grille emblem "fuso" MIS		160	
1	Front panel bt		1636	
1	Front inner upper panel ? repair		2032	XR
2	Front panel side panel LH/RH@2*\$584 de		1168	
1	Wiper garnish de		454	
1	Wiper garnish sticker "canter" ca		124	
2	Wiper arm LH/RH@2*\$138 bt		276	
1	Side mirror rh bt		101	
1	Side mirror arm rh cut		584	
1	Side mirror arm panel garnish rh ca		389	
1	Side mirror arm panel top garnish rh ca		55	
1	Side mirror Lh ca		101	
1	Side round mirror Lh MIS		56	
1	Side mirror arm lh bt		422	
1	Side mirror arm top round cover lh MIS		20	
1	Side mirror arm panel garnish lh ca		389	
1	Side mirror arm panel top garnish rh ca		55	
2	Signal lamp LH/RH@2*\$227 ca		454	
2	Headlamp LH/RH@2*\$635 ca		1270	
2	Side lamp LH/RH@2*\$159 ca		318.00	
1	Tail door bt		2058.00	
2	Tail door hinge LH/RH @4*\$190 X n		760.00	X
2	Tail door lower lock latch LH/RH @2*\$195 X n		390.00	X
2	Tail lamp LH/RH 2*\$229 X n		458.00	X
1	Rear car plate lamp X n		60.00	X
1	Tail door upper latch LH/RH @2*\$180 X n		360.00	X
1	Aircon pipe high pressure bt		290.00	
1	Aircon pipe Low pressure bt		280.00	
1	Cabin front support bar bt		1043.00	
1	Cabin front support bar side bracket RH bt		787.00	
1	Cabin front support bar side bracket LH bt		851.00	

- 2 Cabin front bar side bracket bush LH/RH @2*\$208 *det*
- 1 Dashboard *? cm*
- 1 Roof lining *de*
- 1 Front floor panel *repair bt*
- 1 Front cabin rear panel *repair bt*
- 1 Front windscreen *cm*
- 1 Front windscreen rubber *cm*
- 1 Rear window glass *cm*
- 1 Rear window glass rubber *cm*
- 1 Heater assy *? cm*
- 1 Blower assy *? cm*
- 1 Front door pillar LH/RH (Repair refer to labour) *cm*
- 1 Front cabin rear support railing (Repair refer to labour) *cm*

416.00
1085.00
808.00
1791.00
1648.00
1132.00
493.00
204.00
196.00
3517.00
1012.00
0.00
0.00

100
200 } L 300

30627
252
22,970.25

Part Items
Total:

36725.00
-10% -3672.50
33052.50

SPECIAL NETT ITEMS

- 1 Center grille clips *cm*
- 1 Front Door LH Company Logo Sticker *cm*
- 1 Front Door RH Company Logo Sticker *cm*
- 1 Front panel sticker 'Double S' *cm*
- 1 Front panel sealant *cm*
- 1 Front Car plate *bt*
- 1 Rear Car plate *bt*
- 1 60 km/h sticker *cm*
- 1 24 pax sticker *cm*
- 1 Tail door company detail sticker *cm*
- 1 IU sticker *cm*
- 1 Rear reinforcement beam *bt*
- 2 Canopy rear stand LH/RH (Repair refer to labour) *X cm*
- 2 Front wiper LH/RH @2*\$30 *cm*

50.00 30
180.00 100
180.00 100
180.00 100
60.00 40
35.00
35.00
25.00 10
25.00 10
300.00 200
10.00 5
500.00 300
0.00
60.00 40

985

SN Items Total: 1580.00

Total Parts 34632.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Patrol
Hp 90010068
17 days
L/S
08/04/22 @ 1500
Reqs after repair

Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN2564G MITSUBISHI CANTER FE83BEOSRDEA

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1400
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	60
4	To perform anti-rust treatment on affected areas	90.00	60
5	To remove and replace air-con condenser, pipes, vacuum and recharging gas	120.00	80
6	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	60
7	To remove and refit/replace Front door RH fitting, trimmings, garnish, window glass and lock mechanism	120.00	60
8	To remove and replace front windscreen	150.00	120
9	To remove and refit dashboard and related wire harness and related parts	300.00	150 plus?
10	To remove, replace and focus headlamp beam	60.00	30
11	To remove and replace cabin rear windscreen	100.00	60
12	To remove and replace roof lining	200.00	80
13	To remove and replace cabin front bar with both side bracket	400.00	150
Labour Total :		5750.00	
TOTAL (PARTS & LABOUR):		40382.50	

44447.60

44447.36
60



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN2564G MITSUBISHI CANTER FE83BEOSRDEA

Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Cabin release handle <i>bf</i>		466.00	
1	Cabin inner handle latch <i>bf</i>		207.00	
1	Cabin link lock LH <i>bf</i>		602.00	
1	Cabin link lock RH <i>bf</i>		527.00	
1	Cabin linkage rod <i>bf</i>		110.00	
1	Cabin rear cross member (Repair refer to labour) <i>100 m</i>		0.00	<i>100-L</i>
		<i>1912</i>	1912.00	
		<i>28%</i>	-10% -191.20	
		<i>1434</i>	1720.80	
<u>SPECIAL NETT ITEMS</u>				
1	Chassis member bracket screws <i>m</i>		100.00	<i>30 360</i>
1	Canopy top panel rivet <i>m</i>		80.00	<i>30 360</i>
2	Canopy top panel LH/RH (Repair refer to labour) <i>m</i>	<i>100-L</i>	0.00	
<u>LABOUR</u>				
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components		400.00	<i>200</i>
2	To carried repair and realign rear floor panel to chassis member		400.00	<i>200</i>
3	To carried out remove and refit front cabin		600.00	<i>200</i>
	Total Parts		3300.80	<i>700</i>



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN2564G MITSUBISHI CANTER FE83BEOSRDEA

Page No. 4

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear exhaust pipe front portion (Flexible) <i>bf ✓</i>		567.00	
		<i>567.00</i>		
		<i>25%</i>	567.00	
		<i>425.25</i>	-10%	
			-56.70	
			510.30	
<u>SPECIAL NETT ITEMS</u>				
<u>LABOUR</u>				
1	To remove and replace/refit rear exhaust		300.00	<i>100</i>
		Total Parts	810.30	

22,970.25
300.00
985.00
3910.00
1434.00
100.00
60.00
700.00
425.25
100.00

30,984.50

20%

24,787.60

L/S - \$24,800