



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MINISTRY OF DEFENCE HQ TRANSPORT COMMAND KRANJI CAMP 3 151 CHOA CHU KANG WAYSINGAPORE 688248		Ref: CC2/MIDA22003261/Apq2 Date: 11/10/2022 Code: MIDA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (FOR MANDATE ONLY)</b>			
Insured Veh.	MID 21168	Veh. Inspected	YP 1597H
Policy No.		Coverage (\$)	0.00
Claim No.	CY 22/MID21168/070422/0013	Excess (\$)	0.00
Assign From		Assign Date	08/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	mitsubishi canter	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	FEB50542536	Colour	WHITE
Odometer	163821 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/75 R16C	KAPSEN	6 mm
L/H Front Tyre	205/75 R16C	KAPSEN	6 mm
R/H Rear Tyre	205/75 R16C	KAPSEN	6 mm
L/H Rear Tyre	205/75 R16C	KAPSEN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	07/04/2022	Inspection Date	12/04/2022
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. C)FOR MANDATE ONLY.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>10 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 1597H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DISTORTED	1,112.35	1,112.35
1	BUMPER SIDE (R/H)	NOT NECESSARY	436.71	-
1	FRONT BUMPER BRACKET	BENT	231.17	231.17
1	FOG LIGHT (R/H)	NOT NECESSARY	344.75	-
1	FRONT GRILLE	CRACKED	967.51	698.00
1	FRONT GRILLE EMBLEM	NECESSARY	69.12	69.12
1	EMBLEM "CANTER"	NECESSARY	75.30	75.30
8	FRONT GRILLE CLIP @\$8.00	NECESSARY	64.00	30.00
1	CORNER PANEL (R/H)	TO REPAIR SEE LABOUR	478.41	-
1	FENDER MIRROR GARNISH (R/H)	NOT NECESSARY	91.80	-
2	HEADLIGHT @\$812.95	O/S CRACKED	1,625.90	812.95
1	SIDE LAMP (R/H)	CRACKED	167.05	167.05
2	SIGNAL LAMP @\$248.01	NOT NECESSARY	496.02	-
1	FRONT PANEL	DENTED	1,514.58	1,223.00
1	SET HORN	NOT NECESSARY	107.30	-
1	AIR-CON PIPE (COMPRESSOR-COOLING OIL)	NOT NECESSARY	705.10	-
1	AIR FILTER HOUSING INTAKE	DEFORMED	909.85	458.00
1	AIR RESONATE BOX	NOT NECESSARY	402.10	-
1	RADIATOR EXPANSION TANK	NOT NECESSARY	225.51	-
1	MUDGUARD FRONT (R/H)	DEFORMED	163.32	163.32
1	MUDGUARD FRONT (R/H) (INNER)	NOT NECESSARY	153.10	-
1	BONNET / CABIN RUBBER SEAL (R/H)	NOT NECESSARY	270.76	-
1	BRACKET (CABIN)	BENT	487.70	487.70
1	BRACKET (CABIN / SUPPORT)	DAMAGED	245.10	245.10
1	BRACKET (CABIN / CATCH)	NOT NECESSARY	309.50	-
1	BRACKET (CROSS MEMBER / CABIN)	NOT NECESSARY	938.30	-
1	BONNET / CABIN LOCK	NOT NECESSARY	676.85	-
1	BRACKET (REAR DECK BED ASSEMBLY)	DISTORTED	536.45	536.45
1	SET REAR DECK BED ASSEMBLY	TO REPAIR SEE LABOUR	4,599.50	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,542.00	-
	LESS 25% DISCOUNT		-4,986.78	-1,577.38
			14,960.33	4,732.13



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	REAR CANOPY (SN)	DENTED	1,700.00	900.00
1	REAR FLOOR BOARD (CHECKER PLATE) (SN)	DENTED	2,500.00	800.00
1	STICKER "60KM/H" (SN)	NECESSARY	15.00	15.00
1	STICKER "23 PAX" (SN)	NECESSARY	15.00	15.00
			4,265.00	1,765.00
<b><u>LABOUR</u></b>				
	PANEL BEAT & REPAIR FRONT DAMAGE. INCLUSIVE OF THE REPAIR OF CORNER PANEL (R/H), 1 SET REAR DECK BED ASSEMBLY AND REAR TAILGATE.		1,500.00	1,200.00
	TO PUTTY AND RE-SPRAY AFFECTED PORTION.		1,200.00	1,000.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		150.00	120.00
	TO APPLY UNDERCOATING TO ABOVE AFFECTED.		150.00	80.00
	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS.		50.00	30.00
	TO REMOVE, TRANSFER & DISPOSE RELATED ITEMS.		1,500.00	200.00
	REMOVE & REPLACE / REPAIR AIR-CON. VACUUM & RECHARGE GAS.	NOT NECESSARY	350.00	-
			4,900.00	2,630.00
<b>GRAND TOTAL</b>			<b>24,125.33</b>	<b>9,127.13</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (FOR MANDATE ONLY)</b>				<b>7,300.00</b>

Report Ref No. CC2/MIDA22003261/Apq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. YP 1597H

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. YP 1597H

## RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 1597H

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 1597H

RE-INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YP 1597H

RE-INSPECTION

