



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000283

MINISTRY OF DEFENCE HQ

303 GOMBAK DRIVE

MINDEF BUILDING

SINGAPORE 669645

Xiao Tang

Your Ref. : 21168MID
 Vehicle No. : YP1597H
 Make & Model : MIT CANTER
 Chasis No. : FEB50542536
 Engine No. : 4P10B87308
 Accident Date : 07-04-2022
 Policy No. : 5125847453
 Date : 16-04-2022
 Page : 1 of 3

TEL : 91723389

FAX :

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	FRONT BUMPER <i>Distorted</i>	1.0 PCS	1,112.35	✓ 1,112.35
2	BUMPER SIDE (R/H) <i>Neu</i>	1.0 PCS	436.71	x 436.71
3	FRONT BUMPER BRACKET <i>Best</i>	1.0 PCS	231.17	✓ 231.17
4	FOG LIGHT (R/H) <i>Neu</i>	1.0 PCS	344.75	x 344.75
5	FRONT GRILLE <i>cracked</i>	1.0 PCS	967.51	698 967.51
6	FRONT GRILLE EMBLEM <i>neu</i>	1.0 PCS	69.12	✓ 69.12
7	EMBLEM "CANTER" <i>neu</i>	1.0 PCS	75.30	✓ 75.30
8	FRONT GRILLE CLIP <i>neu</i>	8.0 PCS	8.00	30 64.00
9	CORNER PANEL (R/H) <i>Repair</i>	1.0 PCS	478.41	x 478.41
10	FENDER MIRROR GARNISH (R/H) <i>Neu</i>	1.0 PCS	91.80	x 91.80
11	HEADLIGHT <i>cracked. RH.</i>	2.0 PCS	812.95	812.95 1,625.90
12	SIDE LAMP (R/H) <i>crack</i>	1.0 PCS	167.05	✓ 167.05
13	SIGNAL LAMP <i>Neu</i>	2.0 PCS	248.01	x 496.02
14	FRONT PANEL <i>dented</i>	1.0 PCS	1,514.58	1223 1,514.58
15	HORN <i>Neu</i>	1.0 SET	107.30	x 107.30
16	AIR-CON PIPE (COMPRESSOR - COOLING COIL) <i>Neu</i>	1.0 PCS	705.10	+ 705.10
17	AIR FILTER HOUSING INTAKE <i>detuned</i>	1.0 PCS	909.85	458 909.85
18	AIR RESONATE BOX <i>Neu</i>	1.0 PCS	402.10	x 402.10
19	RADIATOR EXPANSION TANK <i>Neu</i>	1.0 PCS	225.51	x 225.51
20	MUDGUARD FRONT (R/H) <i>detuned</i>	1.0 PCS	163.32	✓ 163.32
21	MUDGUARD FRONT (R/H) (INNER) <i>Neu</i>	1.0 PCS	153.10	+ 153.10
22	BONNET/CABIN RUBBER SEAL (R/H) <i>Neu</i>	1.0 PCS	270.76	x 270.76
23	BRACKET (CABIN) <i>Best</i>	1.0 PCS	487.70	✓ 487.70
24	BRACKET (CABIN/SUPPORT) <i>and</i>	1.0 PCS	245.10	✓ 245.10
25	BRACKET (CABIN/CATCH) <i>Neu</i>	1.0 PCS	309.50	+ 309.50
26	BRACKET (CROSS MEMBER/CABIN) <i>Neu</i>	1.0 PCS	938.30	x 938.30
27	BONNET/CABIN LOCK <i>Neu</i>	1.0 PCS	676.85	+ 676.85



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Reg.No.: 52888887X

QUOTATION

No : QT-000283

MINISTRY OF DEFENCE HQ

303 GOMBAK DRIVE
 MINDEF BUILDING
 SINGAPORE 669645

TEL : 91723389

FAX :

Your Ref. : 21168MID
 Vehicle No. : YP1597H
 Make & Model : MIT CANTER
 Chasis No. : FEB50542536
 Engine No. : 4P10B87308
 Accident Date : 07-04-2022
 Policy No. : 5125847453
 Date : 16-04-2022
 Page : 2 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
28	BRACKET (REAR DECK BED ASSEMBLY) <i>Distorted</i>	1.0	536.45	✓ 536.45
29	REAR DECK BED ASSEMBLY <i>Repair</i>	1.0	4,599.50	✗ 4,599.50
30	REAR TAILGATE <i>Repair</i>	1.0	1,542.00	✗ 1,542.00
31	Discount 25 %			-4,986.78
32	SubTotal (L)			14,960.33
33	FRONT NUMBER PLATE <i>Best</i>	1.0	35.00	✓ 35.00
34	REAR CANOPY <i>Dented</i>	1.0	1,700.00	900 1,700.00
35	REAR FLOOR BOARD (CHECKER PLATE) <i>Dented</i>	1.0	2,500.00	800 2,500.00
36	STICKER "60 km/h" <i>3 new</i>	1.0	15.00	✓ 15.00
37	STICKER "23 pax"	1.0	15.00	✓ 15.00
38	SubTotal (S)			4,265.00
39	PANEL BEAT & REPAIR FRONT DAMAGE	1.0	X	1200 1,500.00
40	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	10W 1,200.00
41	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	1.0	X	120 150.00
42	TO APPLY UNDERCOATING TO ABOVE AFFECTED	1.0	X	80 150.00
43	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X	30 50.00
44	TO REMOVE, TRANSFER & DISPOSE RELATED ITEMS	1.0	X	2630 200. 1,500.00
45	REMOVE & REPLACE / REPAIR AIR-CON.VACUUM & RECHARGE GAS	1.0	X	✗ 350.00
46	SubTotal (LABOUR)			4,900.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000283

MINISTRY OF DEFENCE HQ

303 GOMBAK DRIVE

MINDEF BUILDING

SINGAPORE 669645

TEL : 91723389

FAX :

Your Ref. : 21168MID
Vehicle No. : YP1597H
Make & Model : MIT CANTER
Chasis No. : FEB50542536
Engine No. : 4P10B87308
Accident Date : 07-04-2022
Policy No. : 5125847453
Date : 16-04-2022
Page : 3 of 3

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
------	-------------	-----	-----------------	---------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 9/27.13

1/s : 7.3K.

10 Days

7.3K.

SINGAPORE DOLLAR TWENTY FOUR THOUSAND ONE HUNDRED TWENTY FIVE AND CENTS THIRTY THREE ONLY

E. & O.E

Total	S\$	24,125.33
Discount	S\$	0.00
Net Total	S\$	24,125.33

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.