



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 462L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|--------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 100.00 | 80.00 |
| 1 | CARRIER, BUMPER REAR (SN) | NOT NECESSARY | 775.95 | - |
| 1 | ADAPTER (SN) | BROKEN | 111.35 | 97.99 |
| 1 | ADAPTOR TRIM PANEL REAR (SN) | NOT NECESSARY | 196.70 | - |
| 1 | COVER, TOWING EYE, REAR, PRIMED (SN) | CRACKED | 48.10 | 42.33 |
| 1 | GUIDE, BOTTOM CENTRE (SN) | NOT NECESSARY | 140.70 | - |
| 1 | BUMPER TRIM - M (SN) | CUT | 1,750.85 | 1,386.68 |
| 1 | SET OF MOUNT, BUMPER (SN) | NECESSARY | 69.90 | 46.13 |
| 1 | COVER (SN) | CRACKED | 185.30 | 146.76 |
| 1 | GUIDE (SN) | CRACKED | 168.85 | 148.59 |
| 1 | GUIDE CENTER REAR (SN) | NOT NECESSARY | 236.35 | - |
| 1 | MOUNT RIGHT (SN) | NOT NECESSARY | 159.60 | - |
| 1 | MOUNT LEFT (SN) | NOT NECESSARY | 141.05 | - |
| 4 | PDC SENSOR-ALPINE WHITE (SN) | SHORTED (1PC ONLY) | 1,484.80 | 294.00 |
| 4 | DECOUPLING RING PDC TORQUE CONVERTER (SN) | NECESSARY | 20.60 | 16.52 |
| 7 | PLUG (SN) (ADDITIONAL) | NECESSARY | 6.65 | 5.25 |
| 6 | EXPANDING RIVET (D=8MM) (SN) (ADDITIONAL) | NECESSARY | 6.60 | 5.28 |
| | | | 5,603.35 | 2,269.53 |
| | <u>LABOUR</u> | | | |
| | TO REPLACE REAR BUMPER AND ATTACHMENTS, REAR M DIFFUSER INCLUDE MAKING GOOD THE BOOT LID AND KNOCKING OUT DENTS CAUSED BY THE ACCIDENT. | | 2,520.00 | 720.00 |
| | TO SPRAY PAINT REAR BUMPER, REAR M DIFFUSER AND BOOT LID. | | 2,250.00 | 1,200.00 |
| | TO REPLACE PDC SENSORS AND CONNECTORS INCLUDE RESETTING AND CONDUCTING CHECKS FOR PROPER FUNCTION. | | 350.00 | 280.00 |
| | TO CARRY OUT DIAGNOSIS TESTS. | | 500.00 | 400.00 |
| | | | 5,620.00 | 2,600.00 |
| | GRAND TOTAL | | 11,223.35 | 4,869.53 |

Report Ref No. CS/SMR22003262/Rty3e2



| | | | |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS | | | 4,869.53 |
|-----------------------------|--|--|----------|

Report Ref No. CS/SMR22003262/Rty3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.