

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOM	OTIVE SERVICES PTE LTD	Ref:	CS/SMR22003262/Rty3e2	
	60 WOODLANDS E4SINGAPORE 75	NDUSTRIAL PARK 57705	Date:	10/06/2022	
			Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 959D	Veh. Inspected	SLW 462L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/04/22/2007	Excess (\$)	0.00	
	Assign From	HUA YEN	Assign Date	08/04/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	B.M.W. 520I 2.0L	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WBAXG12010D291434	Colour	WHITE	
	Odometer	114827 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/40Z R19	FALKEN	6 mm	
	L/H Front Tyre	245/40Z R19	FALKEN	6 mm	
	R/H Rear Tyre	245/40Z R19	FALKEN	6 mm	
	L/H Rear Tyre	245/40Z R19	FALKEN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/04/2022	Inspection Date	11/04/2022	
	Survey held at BIS AUTOMOBILES PTE LTD				
		30 TEBAN GARDENS CRESCENT, SINGAPORE 608927			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
$\overline{}$					