

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

Estimate No. : 21998896
Date Estimated : 06/04/2022
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
Mr. LAU WAI KEE

- ACCOUNT -
AXA Insurance Pte Ltd
8 Shenton Way
#24-01
AXA Tower
Singapore 068811
Motor Claims Department

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	
SLW462L	D291434	31/7/2013	520i	
DESCRIPTION		ORIGINAL PRICE	NETT	
To replace rear bumper and attachments, rear M diffuser include making good the boot lid and knocking out dents caused by the accident			2,520.00	
To spray paint rear bumper, rear M diffuser and boot lid			2,250.00	
To replace PDC sensors and connectors include resetting and conducting checks for proper function			350.00	
To carry out Diagnosis Tests			500.00	
Sundries			100.00	
DESCRIPTION		UNIT PRICE	QTY	NETT
51 12 7184769	Carrier, bumper rear	775.95	1.00	775.95
51 12 7299970	Adapter	111.35	1.00	111.35
51 12 8053584	Adaptor trim panel rear	196.70	1.00	196.70
51 12 7240133	Cover, towing eye, rear, primed	48.10	1.00	48.10
51 12 7184765	Guide, bottom centre	140.70	1.00	140.70
51 12 8048594	Bumper trim - M	1,750.85	1.00	1,750.85
51 12 2452063	Set of mount, bumper	69.90	1.00	69.90
51 12 7904994	Cover	185.30	1.00	185.30
51 12 7906845	Guide	168.85	1.00	168.85
51 12 7906292	Guide center rear	236.35	1.00	236.35
51 12 7184768	Mount right	159.60	1.00	159.60
51 12 7184767	Mount left	141.05	1.00	141.05
66 20 9233031	PDC sensor-alpine white	371.20	4.00	1,484.80
66 20 9142107	Decoupling ring PDC torque converter	5.15	4.00	20.60

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

Total Labour :	5,720.00
Total Parts :	5,490.10
Total Labour & Parts :	11,210.10
Deduction for Excess :	
Total Repair Costs less E	11,210.10
GST @7%:	784.71
Grand Total :	11,994.81