

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22003263/UQY3M4**Date:** 19/06/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001958143
<b>Claimant Vehicle No :</b>	SJX7877X	<b>Insured Vehicle No :</b>	SLX4641E
Date of Loss:	04/04/2022	Nature of Claim:	TP
		Claim No:	272291

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJX7877X</b>	Engine No:	046709
Make & Model:	PORSCHE MACAN II, 2.0 PDK E6 (A)	Chassis No:	WP1ZZZ95ZKLB14963
Reg. Date:	03/08/2020 (Man. Year: 2019)	Odometer:	24943 km
Colour:	Blue/Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/40 R20	Rear Tyre Size:	295/55 R21
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	17,411.00	9,086.20	8,324.80	47.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,080.00	2,180.00	51.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>21,671.00</b>	<b>11,166.20</b>	<b>10,504.80</b>	<b>48.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,400.00</b>		
<b>(S\$)</b>	21,671.00	9,400.00	12,271.00	56.62
<b>+ GST 8.00/8.00% (S\$)</b>	1,733.68	752.00	981.68	56.62
<b>Nett Amount (S\$)</b>	<b>23,404.68</b>	<b>10,152.00</b>	<b>13,252.68</b>	<b>56.62</b>

INSPECTION

Date of Assignment:	08/04/2022		
Date Inspected:	14/04/2022	Inspected At:	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711
Estimated Period of Repair:	5.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2023)
<b>Parts:</b> M1-SUV	PORSCHE MACAN II 2.0 PDK E6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJX7877X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Deep Cut	2,000.00 F	*1,750.00 FL
2	1		*REAR BUMPER GARNISH RH	Grazed	258.00 F	*118.00 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
4	1		*REAR BUMPER RETAINER RH	Not Necessary	80.00 F	*- FL
5	1		*REAR FENDER RH	Repair	5,200.00 F	*- FL
6	1		*REAR FENDER COWLING RH	Not Necessary	420.00 F	*- FL
7	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 F	*- FL
8	1		*RIM RH	Warped	4,833.00 FS	*4,833.00 FS
9	1		*REAR QUARTER GLASS SEALANT	Not Necessary	60.00 FS	*- FS
10	1		*REAR FENDER WRAP STICKER	Necessary	900.00 FS	*900.00 FS
11	1		*REAR BUMPER WRAP STICKER	Necessary	1,300.00 FS	*1,000.00 FS
12	1		*REAR FENDER PPF STICKER	Necessary	900.00 FS	*300.00 FS
13	1		*REAR BUMPER PPF STICKER	Necessary	1,300.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>17,411.00</b>	<b>9,281.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	194.80
<b>Total Parts (\$\$)</b>	<b>17,411.00</b>	<b>9,086.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX RH REAR QUARTER GLASS	New	120.00	0.00
2	REMOVE & REFIX INTERIOR TRIMMING, GARNISH, FURNISHER, SEATS, CARPETS ALL AFFECTED PARTS & ETC	New	380.00	150.00
3	REMOVE & REFIX, CUT OUT, RENEW, KNOCKING, WELDING & STRAIGHTEN RH REAR FENDER, REAR BUMPER FASCIA, ALL AFFECTED PARTS & ETC	New	2,200.00	1,000.00
4	SPRAY PAINTING ON DAMAGE	New	900.00	600.00
5	TUFF-KOTE ON DAMAGE PARTS	New	80.00	30.00
6	DIAGNOSTIC AND RESET	New	400.00	200.00
7	COMPUTERIZE WHEEL ALIGNMENT	New	180.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>4,260.00</b>	<b>2,080.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**