

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 09 Jun 2023

Preliminary Advice

Insured Vehicle No	: SLX4641E	Accident Date	: 04/04/2022
TP Vehicle No	: SJX7877X	Assignment Date	: 08/04/2022
Make	: PORSCHE MACAN II	Est. Duration of Repair	: 5
Date of Inspection	: 14/04/2022		
Inspection At	: SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,671.00
Revised Amount	:S\$	11,166.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,166.20
Lump Sum Repair	:S\$	9,400.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	290,000.00
COE / PARF Rebate	:S\$	95,290.00
Salvage Value	:S\$	
Margin for Repair	:S\$	194,710.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.