



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003264/Uvy3n2	
			Date: 12/05/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SG 1699R	Veh. Inspected	SLT 1868J
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/04/22/7001	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	08/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ESTIMA AERAS (A)	c.c	2362
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	ACR500104463	Colour	BLACK
	Odometer	231275 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	CONTINENTAL	5 mm
	L/H Front Tyre	215/60 R17	CONTINENTAL	5 mm
	R/H Rear Tyre	215/60 R17	DUNLOP	5 mm
	L/H Rear Tyre	215/60 R17	DUNLOP	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/04/2022	Inspection Date	08/04/2022
	Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	