



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2204356

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 15/07/2022
Reference CC4/LPC22003274/Kea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMH 7091U
Insured Veh. GBC 4326U
Claim No. 21/22/22/VC00/025658
Policy No. Z/21/VC00/111744
Accident Date 08/04/2022
Inspection Date 11/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC22003274/Kea3q2 Date: 15/07/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 4326U	Veh. Inspected	SMH 7091U	
Policy No.	Z/21/VC00/111744	Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025658	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	08/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP51336962	Colour	METALLIC BLACK	
Odometer	222822 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	FIRENZA	8 mm	
L/H Front Tyre	185/60 R15	FIRENZA	8 mm	
R/H Rear Tyre	185/60 R15	ARIVO	4 mm	
L/H Rear Tyre	185/60 R15	ARIVO	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2022	Inspection Date	11/04/2022	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 7091U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT SIDE MIRROR ASSY LH	DENTED / CUT	715.40	715.40
1	FRONT DOOR LH	BENT	881.20	881.20
1	FRONT DOOR PROTECTIVE STICKER LH	NECESSARY	45.90	45.90
1	FRONT DOOR INNER TRIM BOARD LH	SERVICEABLE	796.20	-
1	REAR DOOR LH	BENT	765.20	765.20
1	REAR DOOR PROTECTIVE STICKET LH	NECESSARY	36.20	36.20
1	REAR DOOR INNER TRIM BOARD LH	SERVICEABLE	766.10	-
1	REAR DOOR RUBBER SEAL LH	DISTORTED	46.80	46.80
1	REAR DOOR UPPER HINGE LH	TO REPAIR SEE LABOUR	46.60	-
1	REAR DOOR LOWER HINGE LH	TO REPAIR SEE LABOUR	46.60	-
1	REAR DOOR CHECKER LH	SERVICEABLE	48.50	-
1	REAR DOOR REGULATOR LH	SERVICEABLE	191.60	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	887.80	-
	LESS 20% DISCOUNT		-1,054.82	-498.14
			4,219.28	1,992.56
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR INNER TRIM BOARD CLIPS LH (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR INNER TRIM BOARD CLIPS LH (SN)	NOT NECESSARY	50.00	-
1	REAR QUARTER GLASS SEALANT LH (SN)	NOT NECESSARY	70.00	-
			170.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF REAR DOOR UPPER HINGE LH ,REAR DOOR LOWER HINGE LH AND REAR FENDER LH.		800.00	500.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH ,REAR DOOR LH ,REAR FENDER LH & ETC.		800.00	650.00
	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF FRONT DOOR LH.		120.00	60.00

Report Ref No. CC4/LPC22003274/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC .TO EFFECT REPLACE OF REAR DOOR LH.		120.00	60.00
	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM ,ROOF LINING & ETC .TO EFFECT REPLACE OF REAR FENDER LH.	NOT NECESSARY	200.00	-
	TO TUFF KOTE & UNDERSEAL MATERIALS.		120.00	60.00
	TO CHECK WIRING & LOCKING SYSTEM.		100.00	20.00
			2,260.00	1,350.00
GRAND TOTAL			6,649.28	3,342.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,650.00

Report Ref No. CC4/LPC22003274/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 7091U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 7091U

RE-INSPECTION

