

Date: 08/04/2022

Vehicle No: SMH7091U

Model: HONDA FIT HYBRID 1.5

Chassis: GP51336962-2018

Reg.Year: 2019

Third Party Insurer: LONPAC

Third Party Veh No: GBC4326U

Date of Accident: 07/04/2022

Estimator: TING AN

Surveyor:

*NOT Notified
L1 Rep &
Resurvey After 5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT SIDE MIRROR ASSY LH	1	Del 60	\$715.40 ✓
2	FRONT DOOR LH	1	Ry	\$881.20 —
3	FRONT DOOR PROTECTIVE STICKER LH	1	na	\$45.90 —
4	FRONT DOOR INNER TRIM BOARD LH	1	Sm	\$796.20 X
5	REAR DOOR LH	1	Ry	\$765.20 ✓
6	REAR DOOR PROTECTIVE STICKER LH	1	na	\$36.20 ✓
7	REAR DOOR INNER TRIM BOARD LH	1	Sm	\$766.10 X
8	REAR DOOR RUBBER SEAL LH	1	Dig	\$46.80 ✓
9	REAR DOOR UPPER HINGE LH	1	R	\$46.60 X
10	REAR DOOR LOWER HINGE LH	1	R	\$46.60 X
11	REAR DOOR CHECKER LH	1	Sm	\$48.50 X
12	REAR DOOR REGULATOR LH	1	Sm	\$191.60 X
13	REAR FENDER LH	1	R	\$887.80 X
			SUB TOTAL	\$5,274.10
			LESS 20%	-\$1,054.82
			PARTS TOTAL	\$4,219.28

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS LH	1	na	\$50.00 X
2	REAR DOOR INNER TRIM BOARD CLIPS LH	1	na	\$50.00 X
3	REAR QUARTER GLASS SEALANT LH	1	na	\$70.00 X
			S/N TOTAL	\$170.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC.

500
\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH & ETC.

\$800.00 *650*

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR LH.

60
\$120.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 08/04/2022

Vehicle No: SMH7091U

Model: HONDA FIT HYBRID 1.5

Chassis: GP51336962-2018

Reg.Year: 2019

Third Party Insurer: LONPAC

Third Party Veh No: GBC4326U

Date of Accident: 07/04/2022

Estimator: TING AN

Surveyor:

na
LABOUR CHARGES TO REMOVE & REINSTALLED ~~FRONT~~ DOOR INNER MECHANISM &
ETC. TO EFFECT REPLACE OF REAR DOOR LH.

\$120.00 *60/*

na
LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM, ROOF LINING &
ETC. TO EFFECT REPLACE OF REAR FENDER LH.

\$200.00 *X*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 *60/*

TO CHECK WIRING & LOCKING SYSTEM.

\$100.00 *20/*

LABOUR TOTAL \$2,260.00

TING AN

TOTAL

\$6,649.28

Head office6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112**Branch**9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993**Branch (Motor Insurance Claims)**Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011