

HOCK WAH MOTOR WORKSHOP PTE LTD

3LK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX6101
TEO CHEW CHUAN
NO

SINGAPORE
TEL : FAX :
PH : 97245771
ATTN :

Term:

ESTIMATE BILL

Number : EB00005934
Date : 08/04/2022
Case No : AD00012564
Vehicle No : SLR6082L
Chassis : VSKDDAC13U0111089
Year of Mfr : 2017
Policy No : 5110906392-02
Model : NISSAN PULSAR

not Allowed
2/5/22
3800/
4 days
Whip it After my

net hitan

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE 305625 137290	1.0	1,485.70	10	1,337.13
2	TAILGATE EMBLEM neu	1.0	74.60	10	67.14
3	TAILGATE LOGO - PULSAR neu	1.0	91.80	10	82.62
4	TAILGATE OUTER HANDLE C/A	1.0	330.40	10	297.36
5	REAR NUMBER PLATE LAMP ^	1.0	92.20	10	82.98
6	REVERSE CAMERA ^	1.0	862.50	10	776.25
7	TAILGATE DAMPER ^	1.0	308.50	10	277.65
8	TAILGATE REFLECTOR RH ^	1.0	570.20	10	513.18
9	TAILGATE REFLECTOR LH ^	1.0	570.20	10	513.18
10	REAR FENDER LAMP LH 7011amp nts cra 466.50	1.0	798.30	10	718.47
11	TAILGATE INNER LOCK 3011/102 108.60	1.0	199.10	10	179.19
12	REAR BUMPER 100/102 886.00	1.0	1,228.70	10	1,105.83
13	REAR BUMPER RETAINER RH 3011 45	1.0	75.70	10	68.13
14	REAR BUMPER RETAINER LH 3011 45	1.0	75.70	10	68.13
15	REAR BUMPER LOWER STICKER n/s	1.0	124.20	10	111.78
16	REAR BUMPER CLIP neu	3.0	6.40	10	17.28
17	REAR BUMPER REINFORCEMENT R	1.0	630.90	10	567.81
18	TAILGATE WINDSCREEN MOULDING neu	1.0	79.90	10	71.91
19	TAILGATE INNER RUBBER ^	1.0	193.20	10	173.88
Nett Price - Parts Sub Total					7,029.90
20	WINDSCREEN SEALANT neu	2.0	24.00	0	48.00
21	REAR NUMBER PLATE 3011	1.0	30.00	0	30.00
22	REAR NUMBER PLATE HOLDER 3011	1.0	30.00	0	30.00
23	REVERSE SENSOR 3011	1.0	280.00	0	280.00
24	END PANEL - REPAIR R X	1.0			
Special Nett Price - Parts Sub Total					388.00
Parts Total					7,417.90
25	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
26	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
27	ANTI-RUST COATING	1.0	150.00	0	150.00
28	WIRING	1.0	80.00	0	80.00
29	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
30	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

2-3520.80
102
3168.81
260
1320
4768.81

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX610I
TEO CHEW CHUAN
NO

SINGAPORE
TEL : FAX :
PH : 97245771
ATTN :

ESTIMATE BILL

Number : EB00005934
Date : 08/04/2022
Case No : AD00012564
Vehicle No : SLR6082L
Chassis: VSKDDAC13U0111089
Year of Mfr 2017
Policy No 5110906392-02
Model : NISSAN PULSAR

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	Labour 1 Sub Total				2,260.00
<u>LKK Auto Consultants hence notify the Repairer of the following:</u> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : TEN THOUSAND THREE HUNDRED FIFTY-FIVE AND CENTS THIRTY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		9,677.90
			GST 7.00%		677.45
			TOTAL		10,355.35

Date of accident : 31/03/2022 06:30 PM. Place : TPE > SENGKANG BEFORE EXIT 9

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE