

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003284/GQY3M4**Date:** 09/09/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00141242100

Claimant Vehicle No : SMT526R **Insured Vehicle No :** SMN537R

Date of Loss: 02/04/2022 Nature of Claim: TP Claim No: SNM22D202324/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT526R**

Make & Model: MAZDA 2, 1.5 HATCHBACK DELUXE 2WD (A) Engine No: P520603618

Reg. Date: 25/03/2020 (Man. Year: 2019) Chassis No: JM6DJ2HAA01300491

Colour: White Odometer: 9204 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R16 Rear Tyre Size: 185/60 R16

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,418.40	2,504.32	1,914.08	43.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,220.00	690.00	36.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,328.40	3,724.32	2,604.08	41.15
+ GST 7.00/7.00% (S\$)	442.99	260.70	182.29	41.15
Nett Amount (S\$)	6,771.39	3,985.02	2,786.37	41.15

INSPECTION

Date of Assignment: 11/04/2022

Date Inspected: 11/04/2022 Inspected At: Vins Automotive Group (Sin Ming) (HQ)
160 Sin Ming Drive, #08-09
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2022)
Parts:	144	MAZDA 2 1.5 HATCHBACK DELUXE 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT526R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Buckled	957.00 FL	*957.00 FL
2	1		*REAR TAILGATE GLASS MOULDING	Necessary	124.00 FL	*124.00 FL
3	1		*REAR TAILGATE EMBLEM	Necessary	62.00 FL	*62.00 FL
4	1		*REAR TAILGATE MAZDA EMBLEM	Necessary	59.00 FL	*35.00 FL
5	1		*REAR TAILGATE 2 EMBLEM	Necessary	44.00 FL	*20.60 FL
6	1		*REAR TAILGATE SKYACTIV TECHNOLOGY EMBLEM	Necessary	68.00 FL	*47.30 FL
7	1		*REAR TAILGATE RH REFLECTOR	Broken	233.00 FL	*233.00 FL
8	1		*REAR TAILGATE LH REFLECTOR	Broken	233.00 FL	*233.00 FL
9	1		*REAR TAILGATE LOWER LOCK	Broken	213.00 FL	*213.00 FL
10	1		*REAR TAILGATE RUBBER	Twisted	169.00 FL	*169.00 FL
11	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	333.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	894.00 FL	*894.00 FL
13	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
14	1		*REAR END PANEL	Repair	478.00 FL	*- FL
15	1		*REAR EXHAUST SILENCER BOX	Not Necessary	1,106.00 FL	*- FL
16	1		*REAR NO. PLATE	Cracked	40.00 FS	*40.00 FS
17	1		*REAR BUMPER PARKING SENSOR	Not Necessary	280.00 FS	*- FS
18	1		*REAR WINDSCREEN GUM	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,423.00	3,107.90
- List Item Discount on L Items 20.00/20.00% (S\$)	1,004.60	603.58
Total Parts (S\$)	4,418.40	2,504.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	TO REPAIR DAMAGES	New	780.00	500.00
3	TO SPRAY PAINTING	New	980.00	600.00
Gross Labour Cost (S\$)			1,910.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >