

Vin's

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Acknowledged by Repairer
Signature:
Date:

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/042022/5335
Date : 11-04-2022
Accident Date : 02-04-2022

Vehicle Details

Make & Model : Mazda MAZDA2 HATCHBACK
1.5 AT DELUXE 2WD
Chassis No : JM6DJ2HAA01300491
Registration No : SMT526R

Third Party Vehicle Details

Registration No : SMN537R

*Pay 5. 11/4/22
P/P before paint job.*

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE <i>Price</i>	1.00	\$957.00
2	REAR TAILGATE GLASS MOULDING <i>/</i>	1.00	\$124.00
3	REAR TAILGATE EMBLEM <i>/</i>	1.00	\$62.00
4	REAR TAILGATE "MAZDA" EMBLEM <i>/</i>	1.00	\$59.00
5	REAR TAILGATE "2" EMBLEM <i>/</i>	1.00	\$44.00
6	REAR TAILGATE "SKYACTIV TECHNOLOGY" EMBLEM <i>/</i>	1.00	\$68.00
7	REAR TAILGATE RH REFLECTOR <i>✓ BR</i>	1.00	\$233.00
8	REAR TAILGATE LH REFLECTOR <i>✓ BR</i>	1.00	\$233.00
9	REAR TAILGATE LOWER LOCK <i>✓ BR</i>	1.00	\$213.00
10	REAR TAILGATE RUBBER <i>✓ TWI</i>	1.00	\$169.00
11	REAR TAILGATE WIPER MOTOR <i>X NN</i>	1.00	\$333.00
12	REAR BUMPER <i>/ Re</i>	1.00	\$894.00
13	REAR BUMPER CLIPS @ \$5.00 <i>/ nbc</i>	10.00	\$50.00
14	REAR END PANEL <i>✗ Repair</i>	1.00	\$478.00
15	REAR EXHAUST SILENCER BOX <i>X NN</i>	1.00	\$1,106.00

Discount: -20%

\$5,023.00
(\$1,004.60)

\$4,018.40

16	REAR NO. PLATE <i>/ cpa</i>	1.00	\$40.00
17	REAR BUMPER PARKING SENSOR <i>✗ NN</i>	1.00	\$280.00
18	REAR WINDSCREEN GUM <i>/ nbc</i>	1.00	\$80.00 50
19	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00 120
20	TO REPAIR DAMAGES	1.00	\$780.00 400 500
21	TO SPRAY PAINTING	1.00	\$980.00 400 600

Subtotal w/o GST:

\$6,328.40

Issued by Raymond Teo

This is a computer-generated document. No signature is required.