

Vin's

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/042022/5335
Date : 11-04-2022
Accident Date : 02-04-2022

Vehicle Details

Make & Model : Mazda MAZDA2 HATCHBACK
1.5 AT DELUXE 2WD
Chassis No : JM6DJ2HAA01300491
Registration No : SMT526R

Third Party Vehicle Details

Registration No : SMN537R

Pay 5. 11/4/22
P/P before paint job.

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE / Price	1.00	\$957.00 ✓
2	REAR TAILGATE GLASS MOULDING /	1.00	\$124.00 ✓
3	REAR TAILGATE EMBLEM /	1.00	\$62.00 ✓
4	REAR TAILGATE "MAZDA" EMBLEM /	1.00	\$59.00 35
5	REAR TAILGATE "2" EMBLEM /	1.00	\$44.00 20.6
6	REAR TAILGATE "SKYACTIV TECHNOLOGY" EMBLEM /	1.00	\$68.00 47.3
7	REAR TAILGATE RH REFLECTOR ✓ BR	1.00	\$233.00 ✓
8	REAR TAILGATE LH REFLECTOR ✓ BR	1.00	\$233.00 ✓
9	REAR TAILGATE LOWER LOCK ✓ BR	1.00	\$213.00 ✓
10	REAR TAILGATE RUBBER ✓ TWI	1.00	\$169.00 ✓
11	REAR TAILGATE WIPER MOTOR X NN	1.00	\$333.00
12	REAR BUMPER / Re	1.00	\$894.00 ✓
13	REAR BUMPER CLIPS @ \$5.00 / nbc	10.00	\$50.00 30
14	REAR END PANEL X Repair	1.00	\$478.00
15	REAR EXHAUST SILENCER BOX X NN	1.00	\$1,106.00
			\$5,023.00 3017.9
Discount: -20%			(\$1,004.60)
			\$4,018.40 2414.32
16	REAR NO. PLATE / cpa	1.00	\$40.00 ✓
17	REAR BUMPER PARKING SENSOR X NN	1.00	\$280.00
18	REAR WINDSCREEN GUM / nbc	1.00	\$80.00 50
19	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00 120
20	TO REPAIR DAMAGES	1.00	\$780.00 400 500
21	TO SPRAY PAINTING	1.00	\$980.00 400 600

Subtotal w/o GST:

\$6,328.40 1310

Issued by Raymond Teo

3724.32

This is a computer-generated document. No signature is required.