

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Sep 2022

Preliminary Advice

Insured : SMD7933L

Vehicle No

TP Vehicle : PC797D
No

Accident Date : 06/04/2022

Make : TOYOTA HIACE

Assignment Date : 11/04/2022

Date of : 14/06/2022

Est. Duration of : 5
Repair

Inspection

Inspection At : MY CAR CONSULTANT PTE LTD (JALAN LAM HUAT) (HQ)
60 JALAN LAM HUAT, CARROS CENTRE #05-21
SINGAPORE 737869

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 8,687.90 |
| Revised Amount | :S\$ | 3,863.98 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,863.98 |

| | | |
|-----------------|------|----------|
| Lump Sum Repair | :S\$ | 3,100.00 |
|-----------------|------|----------|

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |

Margin for Repair

:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.