



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJP831R

Tan

C/O ALLIANZ INSURANCE SINGAPORE
79 Robinson Rd #09-01
Singapore 068897

CT

Vehicle & Document Information

WIP No **56078**
Reg No/Reg Date **SJP831R / 07/03/2018**
Date In/Mileage **26/04/2022 / 80655**
Chassis No **WDD2130452A400350**
Engine No **27492031349711**
Make/Model **MB/MB E 250 2.0 SEDAN (W213) "AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	05/05/2022/ 11:06	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE :SP2000881317-01 // 06.04.2022 DRIVE IN/EXCESS : 08.04.2022 // NIL DATE IN/DATE SURVEY:26.04.2022 // 12.04.2022 RASUL-LKK 15:30PM BY/AUTHORIZED ON : DENISE TAY-LKK//14.06.2022				
M BPNSUN SUNDRIES				15.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPLACE ON REAR BUMPER, BOOT AND ACCIDENT AFFECTED AREA				960.00
A BPIRES RESPRAY ON REAR BUMPER, BOOT AND ACCIDENT AFFECTED AREA				1500.00
X REAR BUMPER	1.00	2093.33	00.00	2093.33
X RIVET	2.00	4.81	00.00	9.62
X GROMMET	3.00	2.64	00.00	7.92
X MERCEDES STAR	1.00	53.84	00.00	53.84
X E250 MODEL PLATE	1.00	94.08	00.00	94.08

Finalization

4 days

Confirmed & accepted by

7% GST on **5,113.79** **357.97**

Authorized signatory and company stamp

Total Payable 5,471.76

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg