

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

AXA Insurance Singapore Pte Ltd
 8 Shenton Way
 # 27-01
 Singapore 068811
 Tel : 6338 - 7288
 Fax : 6880 - 4838

Xiao Tony

Quotation

DATE : 20.04.2022
 VEH NO : GBG5006R
 MODEL : Nissan NV200
 D O A : 05.04.2022
 YR REF : SHC8906Z

Attn : Motor Claim Dept (Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GBG5006R (NISSAN NV200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	NETT ITEMS		
1	Rear Bumper <i>Del'd</i>	1	632.70 ✓
2	Rear Bumper Side Holder - LH & RH <i>Neu</i>	2	86.60 ✓
3	Rear Bumper Reflector - LH & RH <i>Neu Neu</i>	2	85.00 X
4	Rear Bumper Sponge <i>and d.</i>	1	128.90 ✓
5	Rear End Panel Outer <i>Del'd</i>	1	485.20 ✓
6	Rear End Panel Top Garnish <i>Del'd</i>	1	128.40 ✓
7	Rear Door - LH <i>Del'd</i>	1	1,545.00 ✓
8	Rear Door Lower Lock - LH <i>Del'd</i>	1	159.30 ✓
9	Rear Door Inner Trimboard - LH <i>Neu Neu</i>	1	145.20 X
10	Rear Door Outer Garnish <i>Neu</i>	1	351.50 X
11	Nissan Logo <i>Neu</i>	1	64.90 ✓
12	NV200 Emblem <i>Neu</i>	1	88.00 ✓
13	Rear Door - RH <i>Del'd</i>	1	<i>4580.80</i> 1,102.50 ✓
14	Rear Door Lower Lock - RH <i>Del'd</i>	1	159.30 ✓
15	Rear Door Inner Trimboard - RH <i>Del'd</i>	1	<i>4122.72</i> 145.40 X
16	Rear Door Frame Weatherstripe <i>Neu</i>	1	285.90 X
17	Taillamp - LH & RH <i>Neu</i>	2	517.40 X

Less 10%

6,111.20
 (611.12)
 \$ 5,500.08

S/NETT ITEMS

1	Rear Bumper Clips <i>Neu</i>		30.00 ✓
2	Reverse Sensor <i>Del'd</i>		280.00 <i>200</i>
3	Rear End Panel Top Garnish Clips <i>Neu</i>		20.00 <i>10</i>
4	Rear End Panel Sealant <i>Neu</i>		60.00 ✓
5	Rear Door Inner Trimboard Clips - LH <i>Neu Neu</i>		20.00 X

RE : ESTIMATE FOR ACCIDENT REPAIR GBG5006R (NISSAN NV200)

6	Rear Door Outer Garnish Clips - LH	<i>ml</i>	20.00	X
7	Rear Door Glass Sealant - LH	<i>ml</i>	60.00	40
8	Rear Door Inner Trimboard Clips - RH	<i>New ml</i>	20.00	X
9	Rear Door Glass Sealant - RH	<i>ml</i>	60.00	40
10	Floor Panel Top Wooden Board	<i>HPE ml</i>	480.00	X
Total parts			\$	<u>6,550.08</u>

380

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts		\$	1,200.00	<i>800</i>
2	To putty & spray up paint works		\$	1,200.00	<i>800</i>
3	To check wiring system		\$	50.00	<i>30</i>
4	To remove reverse sensor	<i>2020</i>	\$	100.00	<i>50</i>
5	To spray tuff coat		\$	150.00	<i>80</i>
6	To remove upholstery		\$	150.00	<i>40</i>
7	To transfer rear LH & RH door fittings		\$	240.00	<i>100</i>
8	To remove rear LH & RH door glasses		\$	160.00	<i>120</i>
			\$	<u>3,250.00</u>	
Grand Total			\$	<u>9,800.08</u>	

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Total: 6522.72
1/8: 5-2K.
06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: