## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

07.04.22

LKK-

MODEL:

Hyundai loniq 42

INSURANCE: NTUC

VEHICLE NO.: SHC2484M

MVA: LIM T S

T NO.	DESCRIPTION	OTV			THE REAL PROPERTY.		
	Front Bumper	QTY	UNIT	PRICE	STATE OF THE PARTY OF	MOUNT	d
	Front Bumper Clips	1			\$	481.10	
	Front Bumper Upper Moulding	10	\$	2.20	\$	22.00	
	Frt Fender RH	1			\$	368.50	ر کر (
		1			\$	588.80	
	Frt Fender BlueDrive RH	1			\$	26.60	1
	Frt Wheel Cap RH	1			\$	346.40	1
	Headlamp RH	1			\$	2,110.30	-
	DayLight RH	1			\$	642.50	X
	DayLight Grille RH	1			\$	93.45	
	SUB TOTAL LESS 20% TOTAL SPARE PARTS				\$ \$	4,679.65 935.93 <b>3,743.72</b>	
	Labour Charge						
	Panel Beating				\$		-
	Spray Painting				\$		- 1
	Check Wirings Tuff Kote				9		- 1
	Towing Fee				1	NIL	١
	Towning ties					INIL	
	TOTAL LABOU	R			3	1,480.0	0
	ESTIMATE TOTA	<u>.</u>			1	\$ 5,223.7	72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan
82235769
4/201/72 1700
L/S pepuir 2013clay swp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Oale: