



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC22003300/Vqy3e2 Date: 11/05/2022 Code: LPC2	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GBH 1561A	Veh. Inspected	SKX 8347R	
Policy No.	Z22VC05009838	Coverage (\$)	0.00	
Claim No.	22/22/22VC05/025643	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	11/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 216D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA2B32090V259765	Colour	BROWN	
Odometer	198255 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	BRIDGESTONE	7 mm	
L/H Front Tyre	205/55R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	205/55R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/55R16	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
<b>5. General Information</b>				
Accident Date	04/04/2022	Inspection Date	13/04/2022	
Survey held at	CHNG BROTHER MOTOR SERVICE 2 KAKI BUKIT AVENUE 2 #02-32 KAKI BUKIT AUTOHUB SINGAPORE 417921.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				