

TP Allianz
Veron.

Vernon.

Reference: SMK9189T
RENAULT /
GRAND SCENIC
IV 1.5 DCI AT
Make: EU6

Dear Sir,

RE: VEHICLE.:SMK9189T
CHASSIS NO.:VF1RFA00362476752
ENGINE NO.:K9KF649D059639

Name of insured : ALPINE CAR RENTAL PTE LTD
Date of accident.: 01/04/2022

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

No.	Qty	Part Description	Price (SGD)
<u>1</u>	1	RR TAILGATE INNER	\$ 1,100.00
<u>2</u>	1	RR TAILGATE OUTER	\$ 2,500.00
<u>3</u>	1	RR TAILGATE GLASS	\$ 940.00
<u>4</u>	1	RR TAILGATE LOGO	\$ 250.00
<u>5</u>	1	RR TAILGATE SCENIC EMBLEM	\$ 216.00
<u>6</u>	1	RR TAILGATE RENAULT EMBLEM	\$ 216.00
<u>7</u>	1	RR TAILGATE LOCK	\$ 280.00
<u>8</u>	1	RR TAILGATE LOCK CATCHER - Striker	\$ -
<u>9</u>	1	RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	\$ -
<u>10</u>	1	RR TAILGATE WEATHERSTRIP	\$ -
<u>11</u>	1	RR TAILGATE INNER TRIM BOARD LOWER	\$ -
<u>12</u>	1	RR TAILGATE INNER TRIM BOARD CLIP	\$ 20.00
<u>13</u>	1	RR BUMPER UPPER	\$ 1,760.00
<u>14</u>	1	REAR BUMPER MIDDLE (BLACK)	\$ 1,080.00
<u>15</u>	1	REAR BUMPER MIDDLE (SILVER)	\$ 780.00
<u>16</u>	1	REAR BUMPER LOWER	\$ 520.00
<u>17</u>	1	REAR BUMPER REVERSE SENSOR	\$ 400.00

$\frac{+}{-}$ 845
 $\frac{+}{-}$ 161
 $\frac{-}{-}$ 138
 $\frac{-}{-}$ 152
 $\frac{+}{-}$
 $\frac{+}{-}$
 $\frac{+}{-}$
 $\frac{+}{-}$
 $\frac{+}{-}$
 $\frac{+}{-}$
 $\frac{-}{-}$ 1386
 $\frac{-}{-}$ 689
 $\frac{-}{-}$ 486
 $\frac{+}{-}$

18	1	RR BUMPER REFLECTOR RH	2	\$ 340.00	+
19	1	RR BUMPER REFLECTOR LH	1	\$ 340.00	+
20	1	RR BUMPER TOW COVER	1	\$ 120.00	+
21	1	REAR BUMPER REINFORCEMENT	Dented.	\$ 1,280.00	686
22	1	RR END PANEL INNER	3	\$ -	+
23	1	RR END PANEL OUTER - Lower	1	\$ -	+
24	1	RR END PANEL TOP GARNISH	1	\$ -	+
25	1	RR BUMPER SIDE RETAINER RH(OUTER)	2	\$ 440.00	+
26	1	RR BUMPER SIDE RETAINER RH(INNER)	1	\$ 440.00	+
27	1	RR BUMPER SIDE RETAINER LH(OUTER)	1	\$ 440.00	+
28	1	RR BUMPER SIDE RETAINER LH(INNER)	1	\$ 440.00	+
29	1	RR BUMPER RETAINER TOP CENTRE	1	\$ 500.00	+
30	1	RR BUMPER BRACKET LOW RH	1	\$ 440.00	+
31	1	RR BUMPER BRACKET LOW LH	1	\$ 440.00	+

5063

Parts Total: \$ 15,282.00

Less 10%: \$ 1,528.20

4556.70

Total : \$ 13,753.80

Labour

Labour Description

No. Price (SGD)

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,200.00	500
2	Carry out spray painting on accident affected area	\$ 1,200.00	500
3	To conduct anti rust of under carriage tuff coat	\$ 120.00	+
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	30
5	To remove and refix reverse sensor and conduct test	\$ 80.00	50
6	To remove and refix reverse camera and conduct test	\$ 80.00	50
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 120.00	80
8	To conduct water leakage test after repairs of vehicle	\$ 120.00	+
9	To remove and refix rear tail gate windscreen	\$ 120.00	✓

1330

Labour Total : \$ 3,160.00

Others

Other Description

No. Qty Price (SGD)

Rear portion

1	1	Rear Tailgate Windscreen sealant	120.00 <i>120.00</i>	\$ 120.00	60 <i>+</i>
2	1	Rear end panel insulation seal	<i>120.00</i>	\$ 120.00	<i>+</i>

Other Total: \$ 240.00

Total: \$ 17,153.80
GST 7%: \$ 1,200.77
GRAND TOTAL: \$ 18,354.57

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

 **Suhaimi Ong**

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax: 6844 5185

Adrian Lj
P/P 11/04/22

04 Days.

total: 5886.70
(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: