

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: SMW6818T
 Vehicle Model : Honda Shuttle Hybrid 1.5 Auto
 Manufacturing Year : 2018
 Chassis : GP72002951

TP AXA-
Veron.

S/N.	Item Description	Amount (\$)
1	Front Bonnet <i>Distorted</i>	\$ 849.60
2	Front Bonnet Hinge x 2 pcs <i>Best</i>	\$ 77.88
3	Front Bonnet Rubber <i>lt</i>	\$ 26.55
4	Front Bonnet Undercover <i>cracked</i>	\$ 123.90
5	Front Bonnet Undercover Clip x 1 set <i>nr</i>	\$ 50.00
6	Front Bonnet Lock <i>Dist</i>	\$ 123.90
7	Front Bonnet Lock Cable <i>damaged</i>	\$ 61.95
8	Front Bonnet Lock Garnish <i>Deformed</i>	\$ 58.60
9	Front Bonnet Stand <i>xtl nr</i>	\$ 68.40
10	Front Bumper <i>Distorted</i>	\$ 849.60
11	Front Bumper Side Bracket x 2 pcs <i>damd</i>	\$ 21.24
12	Front Bumper Clip x 6 pcs <i>nr</i>	\$ 21.24
13	Front Bumper Lower Grille (Centre) <i>Dehd.</i>	\$ 115.05
14	Front Bumper Reinforcement <i>Best.</i>	\$ 371.70
15	Front Bumper Side Cover (Top) x 2 pcs (no. 11) <i>2 LH</i>	\$ 70.80
16	Front Bumper Side Cover (Bottom) x 2 pcs (No. 10) <i>Dehd</i>	\$ 53.10
17	Front Engine Undercover (no. 7) <i>Deformed.</i>	\$ 189.20
18	Front Grille Assy (no. 2 + 3 + 4 + 6) <i>cracked.</i>	\$ 778.80
19	Front Grille Cover <i>Dist</i>	\$ 56.80
20	Honda Centre Logo <i>xtl</i>	\$ 26.55
21	Front Fender 2 pcs <i>xtl Buckled.</i>	\$ 460.20
22	Front Fender Inner Garnish x 2 pcs <i>LH torn</i>	\$ 247.80
23	"Hybrid" Emblem x 2 pcs <i>NEC</i>	\$ 142.12
24	Front Door Pillar (LH) <i>xtl nr</i>	\$ 526.00
25	Headlamp x 2 pcs (No. 9) <i>LH cracked, RH cut</i>	\$ 1,699.20
26	Headlamp Lower Retainer (LH) <i>crackd</i>	\$ 49.56
27	Front Windscreen Moulding x 1 set <i>xtl nr</i>	\$ 129.80
28	Front Wiper Garnish (Centre) <i>cut</i>	\$ 283.20
29	Front Wiper Garnish (Side) x 2 pcs <i>LH Dist</i>	\$ 95.60
30	Horn <i>Distorted</i>	\$ 44.25
31	Front Support Panel <i>Distorted</i>	\$ 654.90
32	Front Support Panel Top Garnish <i>Dehd</i>	\$ 61.95
33	Front Wheelhouse (LH) <i>Buckled.</i>	\$ 985.60
34	Front Shock Absorber (LH) <i>xtl nr</i>	\$ 345.15

✓
✓
✓
✓
30.
✓
✓
✓
x.
✓
✓
✓
✓
35.40
26.55
✓
✓
✓
123.80.
✓
x.
✓
x.
47.80.
✓
✓
x.

1	Front Tyre Rim (LH) <i>new</i>	\$	580.00	
2	Front Tyre (LH) <i>new</i>	\$	280.00	
3	Battery <i>new</i>	\$	180.00	
4	Front Number Plate with Casing <i>Dupd</i>	\$	60.00	
5	Front Windscreen Sealant <i>new</i>	\$	80.00	
6	Radiator Coolant <i>new</i>	\$	80.00	
7	Gearbox Oil <i>new</i>		100	120
Amount :		\$	1,260.00	

Labour		Amount (\$)	
Towing charges	\$	120.00	60.
To conduct 4 wheel alignment	\$	80.00	✓
To check front electrical wiring & focus headlamps	\$	180.00	30
To conduct computer diagnostic & resetting	\$	380.00	200
To remove & install radiator, a/c condenser, a/c piping etc and refill a/c gas	\$	180.00	120
To remove & reinstall front undercarriages	\$	380.00	200.
To remove & reinstall front dashboard	\$	400.00	220.
To remove & install front windscreen & LHF fender glass to facilitate repair	\$	300.00	60 X.
To remove & reinstall interior trims & garnishes to facilitate repair	\$	220.00	100.
To remove & install airbags, airbag control unit, seatbelts and do programming	\$	350.00	300
To remove & install front tyre & rim, and conduct tyre balancing	\$	80.00	X.
To conduct chassis alignment	\$	300.00	200
To remove & install engine unit to facilitate repair	\$	400.00	350
To apply anti-rusting coating on new & affected panels	\$	250.00	120.
Labour to remove, cut, change & panel beating	\$	3,800.00	1500
To putty and respray affected areas	\$	2,800.00	1400.
Labour Total :		\$	10,220.00
Total (Parts & Labour)		\$	37,015.38

37,135.38

total: 20602.87

2/5: 16.4K.

14 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____