

AP AUTOMOTIVE SERVICES PTE LTD ROC / GST REG NO : 202022890H BLOCK 9006 TAMPINES STREET 93 #01-202 SINGAPORE 528840 TEL: 6784 4465 FAX: 6787 4886

ESTIMATION

DATE:

VEHICLE :

SJF3254P

MAKE / MODEL:

WDB2110412B068959

| No. | Description | Unit | Unit Price | Amount |
|-----|-------------------------------------|------|------------|----------------------|
| | PART REPLACEMENT | | | . 1 |
| | FRONT BUMPER \280 (\$55) | 1 | \$1,430.00 | \$ 1,430.00 |
| | FRONT BUMPER FRAME | 1 | \$116.00 | \$ 116.00 |
| | FRONT BUMPER SIDE FRAME | 1 | \$61.00 | \$ 61.00 - 05 |
| 1 | FRONT BUMPER SIDE BRACKET | 12 | \$85.00 | \$ 170.00 |
| | FRONT BUMPER PROTECTOR RH | 1 | \$440.00 | \$ 440.00 CUL |
| | FRONT BUMPER CHROME MOULDING RH | 1 | \$269.00 | \$ 269.00 CUL |
| | FRONT BUMPER SIDE GRILLE RH | 7, 1 | \$21.00 | \$ 21.00 × NS |
| | FRONT BUMPER LOW GRILLE | 1 | \$78.00 | \$ 78.00 XSVC |
| | FRONT BUMPER REINFORCEMENT 400 | 1 | \$681.00 | \$ 681.00 NT |
| | FRONT BUMPER REINFORCEMENT ABSORBER | 021 | \$245.00 | \$ 490.00 cra |
| - | FRONT BUMPER SIDE FRAME RH | 1 | \$72.00 | \$ 72.00 - 11 5 |
| | FRONT BUMPER SPONGE 4-0 | 1 | \$60.00 | \$ 60.00 X NS |
| | FRONT BUMPER BRACKET RH | 1 | \$87.00 | \$ 87.00 ALSXNS |
| | FRONT BUMPER FOG RH | 1 | \$320.00 | \$ 320.00 -Crn |
| | FRONT BUMPER FOG LAMP GARNISH RH | 1 | \$142.00 | \$ 142.00 Cat |
| | FRONT BUMPER LOWER COVER | 1 | \$221.00 | \$ 221.00 CRA |
| | FRONT BUMPER NUMBER PLATE GARNISH | 1 | \$160.00 | \$ 160.00 \$50 |
| | FRONT HEAD LAMP RH | 1 | \$1,125.00 | \$ 1,125.00 - CVG |
| | FRONT HEAD LAMP PANEL RH | 1 | \$122.00 | \$ 122.00 - (۷ 9 |
| | FRONT HEAD LAMP WIRE HARNESS | 1 | \$320.00 | \$ 320.00% gxc(4+ |
| | A/C CONDENSER | 1 | \$1,125.00 | \$ 1,125.00 XHN |
| | A/C CONDENSER DRIER | 1 | \$245.00 | \$ 245.00 × NS |
| 8 | A/C CONDENSER HIGH PRESSURE HOSE | 2 | \$312.00 | \$ 624.00 1× NA |
| | A/C CONDENSER LOWER PRESSURE HOSE | 2 | \$284.00 | \$ 568.00 X NN |
| | RADIATOR | 1 | \$2,162.00 | \$ 2,162.001×HH |
| | RADIATOR FAN | 1 | \$1,159.00 | \$ 1,159.00 |
| | RADIATOR FASTENER | 2 | \$18.00 | \$ 36.00 X HN |
| | RADIATOR TOP HOSE | 1 | \$82.00 | \$ 82.00 XHN |
| | RADIATOR BOTTOM HOSE | 1 | \$112.00 | \$ 112.00 XHN |
| | RADIATOR BUSH | 2 | \$11.00 | \$ 22.00 XXX |
| | RADIATOR BOTTOM TOP AIR DUCT | 1 | \$512.00 | \$ 512.00 NN |
| | RADIATOR BOTTOM BOTTOM AIR DUCT | 1 | \$63.00 | \$ 63.007 X H H |
| | RADIATOR FAN HOUSING | 1 | \$264.00 | \$ 264.007 XNN |
| | INTERCOOLER | 1 | \$621.00 | \$ 621.00 XXX |
| | INTERCOOLER INTAKE PIPE | 1 | \$259.00 | \$ 259.00 |
| | INTERCOOLER OUTLET PIPE | 1 | \$367.00 | \$ 367.00 XNN |

| AIR INTAKE HOSE | | \$320.00 | \$ | 320.007 |
|---|------|----------------------|----|--|
| POWER STEERING COOLER PIPE | 1 | \$280.00 | \$ | 280.00 📉 |
| FRONT HORN | 2 | \$142.00 | \$ | 284.00 |
| FRONT BONNET | 1 | \$2,464.00 | \$ | 2,464.00 |
| FRONT BUMPER LOGO | 1 | \$180.00 | \$ | 180.00 ne |
| FRONT BONNET GRILLE | 1 | \$512.00 | \$ | 512.00 |
| FRONT BONNET CABLE | 1 | \$96.00 | \$ | 96.00 P |
| FRONT BONNET INSULATOR | 1 | \$148.00 | \$ | 148.00 |
| FRONT BONNET HINGE | 2 | \$134.00 | \$ | 268.00-54 |
| FRONT BONNET DAMPER | 2 | \$127.00 | \$ | 254.00 \$ 5 |
| FRONT BONNET CENTRE LOCK | 1 | \$57.00 | \$ | 57.00- ; 0 |
| FRONT BONNET SIDE LOCK | 2 | \$76.00 | \$ | 152.00 |
| FRONT BOONET LOCK COVER | | \$46.00 | \$ | 92.00 (4 |
| FRONT BONNET CENTRE UPPER LOCK | | \$68.00 | \$ | 68.00 34 |
| FRONT BONNET STOPPER | _ | \$48.00 | \$ | 48.00 n |
| FRONT FENDER RH | _ | \$958.00 | \$ | 958.00 |
| FRONT FENDER INNER SHIELD FRONT RH | | \$172.00 | \$ | 172.00 |
| FRONT FENDER INNER SHIELD REAR RH | _ | \$180.00 | \$ | 180.00 X SU |
| FRONT FENDER COVER RH | | \$210.00 | \$ | 15 210.00 |
| FRONT DOOR RH TOP HINGE | | \$183.00 | \$ | 183.00 |
| FRONT DOOR RH LOWER HINGE | _ | \$183.00 | \$ | 183.00 x S |
| FRONT DOOR RH CHECKER | _ | \$152.00 | \$ | 152.00 Wi |
| FRONT WHEEL HOUSE RH | | \$2,712.00 | \$ | 2,712.00 × 5 |
| FRONT CHASSIS END | _ | \$222.00 | \$ | 444.00 |
| FRONT CHASSIS END PLATE | | \$157.00 | \$ | 314.00 |
| FRONT SUPPORT PANEL CENTRE | - | \$116.00 | \$ | 116.00 |
| FRONT SUPPORT PANEL LH & RH | | \$108.00 | \$ | 216.00 |
| FRONT SUPPORT HEADLAMP BRACKET | | \$87.00 | \$ | 174.00 CV |
| FRONT SUPPORT CENTRE BRACE | | \$76.00 | \$ | 76.00 |
| FRONT SUPPORT WEATHERSTRIP | _ | \$176.00 | \$ | |
| FRONT SHOCK ABSORBER RH | | \$866.00 | \$ | 176.00 1 X |
| FRONT SHOCK ABSORBER SPRING RH | | \$378.00 | \$ | 378.00 |
| FRONT SHOCK ABSORBER MOUNTING RH | | \$256.00 | \$ | 1 |
| FRONT SHOCK ABSORBER RUBBER BUMPER RH | | \$78.00 | \$ | 256.00 78.00 . × |
| FRONT SHOCK ABSORBER COVER RH | | \$59.00 | \$ | |
| FRONT SHOCK ABSORBER DUST CAP RH | | \$39.00 | \$ | 59.00 1 |
| FRONT UPPER ARM RH | | \$579.00 | \$ | 39.00 ¹ ,× _5 79.00 1.* |
| FRONT KNUCKLE ARM RH | | \$1,298.00 | \$ | 1,036 1,298.00 |
| FRONT KNUCKLE ARM WHEEL HUB BEARING RH | | \$795.00 | \$ | 3.8 Z95.00 1. D |
| FRONT LOWER ARM RH | | \$648.00 | \$ | 548 648.00 1.00 |
| FRONT CONTROL ARM RH | | | | 679.00 |
| FRONT TIE ROD RH | | \$679.00 \$146.00 | \$ | 146.00 |
| | | - | _ | 107.00 / * |
| FRONT LINK ROD RH | | \$197.00 | \$ | 197.00 |
| FRONT BRAKE ROTOR RH FRONT BRAKE CALIPER RH | | \$364.00 | \$ | 364.00 |
| | | \$824.00 | \$ | 824.00 1 |
| FRONT ABS SENSOR RH | | \$385.00 | \$ | 385.00 1X |
| FRONT ABDAG SEASON | | \$2,800.00 | \$ | 2,800.00 |
| FRONT AIRBAG SENSOR | | \$248.00 | \$ | 248.00 1,976.00 |
| AIRBAG SENSOR ECU | 2.20 | \$1,976.00 | \$ | |

| | | Sub Total | \$ 43,943.20 |
|--------------------------------|---|------------------|----------------------|
| | | Less 5% | \$ 2,312.80 |
| | | Total | \$ 46,256.00 |
| FRONT WIPER GARNISH | 1 | \$352.00 | \$ 352.00 MXSVC |
| FRONT WINDOW GLASS SENOR | 1 | \$156.00 | \$ 156.00 ne KNI |
| FRONT WINDSCREEN GARNISH RH | 1 | \$178.00 | \$ 178.00 1× 10 N |
| FRONT WINDSCREEN | 1 | \$1,475.00 | \$ 1,475.00 Cra |
| FRONT SAFETY BELT | 2 | \$1,875.00 | \$ 3,750.00 1XNN |
| FRONT PASSENGER SEAT AIRBAG RH | 1 | \$783.00 | \$ 783.00 ACT |

| S/NETT ITEMS | | | |
|---------------------------------------|----|------------|--|
| FRONT BUMPER CLIPS (SET) | 1 | \$80.00 | \$ 80.00 30 he |
| FRONT FENDER INNER SHIELD CLIPS (SET) | 1 | \$80.00 | \$ 80.00 30 nel |
| FRONT SUPPORT CLIP (SET) | 1 | \$60.00 | \$ 60.00 3 0 MM |
| FRONT ENGINE UNDERCOVER CLIP (SET) | 1 | \$80.00 | \$ 80.00 30 nee |
| FRONT BUMPER AIR DELFECTOR CLIP (SET) | 1 | \$60.00 | \$ 60.00 30 nic |
| POWER STEERING FLUID | 4 | \$140.00 | \$ 560.00 7.×NN |
| WATER COOLANT | 4 | \$69.00 | \$ 276.00 0.40 NEC 240.00 7.30 NEC |
| BRAKE FLUID | 4 | \$60.00 | \$ 240.00 X 30 NEC |
| FRONT WINDOW GLASS SOLAR FILM | 1 | \$400.00 | \$ 400.00 150 nac |
| UNDERCARRIAGE BOLTS | 12 | \$12.00 | \$ 144.00 60 nec 5 |
| FRONT WHEEL TYRE 60% cut | 1 | \$800.00 | \$ 500 800.00 200 60 0 30 |
| SPORT RIM | 1 | \$1,800.00 | \$ 21,800.00 (va |
| FRONT NUMBER PLATE | 1 | \$55.00 | \$ 55.00 KSVC |
| | | Total | \$ 2,799.00 |

LABOUR

| | | | repender Of | HE IUIO | WHILI | |
|------------------------------|----------------|---------|-------------|----------|-----------|--|
| 1 | Part Re | eplacen | ent Amount | S follow | 46,742.20 | |
| TO APPLY RUST PROOFING | | 1 | \$240.00 | tante h | 240.00 | KUM X Lobers, |
| REFOCUS HEADLIGHTS | | 1 | \$120.00 | \$ | 120.00 | SHOW SELLING TO SELLIN |
| ECU DIAGNOSTIC AND CLEARING | FAULT CODES | 1 | \$180.00 | \$ | 180.00 | CANON DO |
| REPROGRAM AIRBAG ECU | | 1 | \$300.00 | \$ | 300,00 | m Co |
| REPROGRAM ABS PUMP | | 1 | \$300.00 | \$ | 300.00 | 2120 |
| REMOVE AND REFIT FRONT WIND | OW GLASS | 1 | \$220.00 | \$ | 220.00 | 110 |
| REMOVE AND REFIT A/C CONDEN | SER & RADIATOR | 1 | \$400.00 | \$ | 400.00 | 2X represed |
| REMOVE AND REFIT ABS PUMP. B | LEEDING | 1 | \$320.00 | \$ | 320.00 | 180 steel |
| TO APPLY RUST PROOFING | | 1 | \$240.00 | \$ | 240.00 | 100 |
| REFOCUS HEADLIGHTS | | 1 | \$200.00 | \$ | 200.00 | 86 |
| VACCUM AND REFILL A/C GAS | | 1 | \$240.00 | \$ | 240.00 | [הר |
| REMOVE AND REFIT A/C CONDEN | SER & RADIATOR | 1 | \$400.00 | \$ | 400.00 | 150 |
| CONDUCT 4 WHEEL ALIGNMENT | | 1 | \$400.00 | \$ | 400.00 | 60 |
| CONDUCT CHASSIS ALIGNMENT | | 1 | \$240.00 | \$ | 240.00 | no |
| REMOVE AND REFIT UNDERCARRI | IAGE | 1 | \$800.00 | \$ | 800.00 | 3660150 |
| SPRAY PAINTING ON AFFECTED A | REAS | 1 | \$1,600.00 | \$ | 1,600.00 | 1000 |
| PANEL BEATING ON AFFECTED AR | EAS | 1 | \$2,400.00 | \$ | 2,400.00 | 1000 |
| LABOUR | | _ | | | | 7. |

Though echhauto 10m 82235769 12/4/22 1300

Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

Total Amount d\$art(s) during 55,342.20

No illegal modification(s) is allowed

Total Amount FourLabourd \$er spray painting,600.00

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Constito

1300 LIS rapair 7 days wp