

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 13 Oct 2022

**Preliminary Advice**

Insured Vehicle No	: GBF9042P	Accident Date	: 06/04/2022
TP Vehicle No	: SJF3254P	Assignment Date	: 16/04/2022
Make	: MERCEDES-BENZ E200K	Est. Duration of Repair	: 7
Date of Inspection	: 12/04/2022		
Inspection At	: AP AUTO (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BLDG SINGAPORE 508775		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,342.20
Revised Amount	:S\$	21,892.15
Check Items (Estimated)	:S\$	0.00
Total	:S\$	21,892.15
 Lump Sum Repair	 :S\$	 17,000.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.