



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003319/Uqy3n2 Date: 18/05/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 4967H	Veh. Inspected	SLT 7347G
	Policy No.		Coverage (\$)	0.00
	Claim No.	BALAI SCL2022-00011SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	11/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	NHP1707069671	Colour	YELLOW
	Odometer	120259 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FIRENZA	6 mm
	L/H Front Tyre	185/60 R15	FIRENZA	6 mm
	R/H Rear Tyre	185/60 R15	FIRENZA	6 mm
	L/H Rear Tyre	185/60 R15	FIRENZA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/04/2022	Inspection Date	21/04/2022
	Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	