

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CS/A1522003319/Uqy3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLT 7347G
at Workshop m/s Reliable cars #0550
of _____
Insured: SLP 4967H
Policy No. _____
Claims No. BALAISCL2022-00011SL
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLT7347G Yr Regn: 09/11/17
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (A) Hybrid
Make: Toyota Sienta c.c 1496
Colour: Yellow A/C: Insured / Std / NI / NA
Sp. Reading: 120259 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: NHP 170 7069671
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/60R15
R: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Firestone
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 06/04/22 D.O.I. 21/4/22
Survey held at _____

Bal. or Market Value: \$67k.
IDAC Accident Rport: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lump Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS C 527N
Date: _____ Person Contacted: Jason 81669797
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/4/22	LTA \$2750 De \$1500

21/4/22 L/S \$3400 informed Jason. (Red \$4542.36, 57%)

Date/Time, File Pass to? : Preli. Report
1) 29/04 Typist : Final Report
Date/Time, File Return to?

Days Of Repair: 4
Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
_____ S + RS, ___ SI	
Photos	
Others	
TOTAL	

Report Format : TP
Lump Sum / ~~PL~~ (\$ 3400)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Email: reliablecarzpl@gmail.com

*not authorized
rel
new
9009 6608
21/4/22
Telok Ayer St. 4 days.
REF: RC3339*

1/5 \$3400

Vehicle No.: SLT7347G

Model: TOYOTA SIENTA

REF: RC3339

QTY DESCRIPTION

AMOUNT (\$S)

List Items:

1	Rear bumper	<i>no/ok</i>	572.45	—
2	Rear bumper retainer @S\$82.45	<i>11</i>	164.90	X
2	Rear bumper bracket @S\$93.96	<i>11</i>	187.92	X
2	Rear bumper reflector @S\$90.48	<i>11</i>	180.96	X
1	Rear bumper protector (Center)	<i>grated</i>	217.45	—
1	Rear bumper protector side RH	<i>7M</i>	152.45	—
1	Rear bumper protector side LH	<i>7M</i>	152.45	—
2	Tail lamp @S\$477.25	<i>11</i>	954.50	X
1	Tailgate	<i>3rd 500</i>	1198.50	—
1	Tailgate lock	<i>no/ok</i>	341.90	—
1	Tailgate emblem (Logo)	<i>new</i>	66.78	—
2	Tailgate hinge @ S\$38.12	<i>11</i>	76.23	X
1	Tailgate inner board	<i>11</i>	510.96	X
1	Rear end panel	<i>R</i>	552.45	X
1	Rear end panel top garnish	<i>7M</i>	241.10	—
2	Rear windscreen moulding side @ S\$60.35	<i>new</i>	120.70	—
			<u>6052.95</u>	
			Less 20%	(1210.59)
			<u>Subtotal</u>	<u>4842.36</u>

Special Nett Items:

	Rear bumper clip (set)	<i>new</i>	60.00	<i>50</i>
<i>1 set</i>	Reverse sensor	<i>5 units</i>	300.00	<i>200</i>
	Rear number plate & base	<i>new</i>	60.00	<i>X</i>
	Rear windscreen sealant	<i>new</i>	80.00	<i>40</i>
	<u>Subtotal</u>		<u>500.00</u>	

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875
Contact No.: +65 8166 9797 Fax No.: +65 6385 1751
Email: reliablecarzpl@gmail.com

Vehicle No.: SLT7347G

Model: TOYOTA SIENTA

REF: RC3339

Labour Charges:

To apply undercoating	150.00	↳
To remove & refix reverse sensor system	150.00	↳
To remove & refix inner trim for facilities repair	120.00	↳
To panel beating	1000.00	↳
To spray painting on affected area	1000.00	↳
To remove & refix rear windscreen glass	180.00	↳
Subtotal	2600.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

7,942.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3063-78
25%
P-2297-83
S.N-290
L-1700
4287-83
202
3430