



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003321/Eqy3n2	
			Date: 31/05/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1089H	Veh. Inspected	SLN 6616T
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/22/2003	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	11/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	BMW 530I	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBAJA520X0WA34200	Colour	BLUE
	Odometer	117412 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R19	MICHELIN	4 mm
	L/H Front Tyre	245/40 R19	MICHELIN	4 mm
	R/H Rear Tyre	245/40 R19	MICHELIN	4 mm
	L/H Rear Tyre	245/40 R19	MICHELIN	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/04/2022	Inspection Date	04/05/2022
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	