

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22003322/KVY3N2**Date:** 29/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00265452100		
Claimant Vehicle No :	SKM7818M	Insured Vehicle No :	SMS146J		
Date of Loss:	29/03/2022	Nature of Claim:	TP	Claim No:	SNM22D202453/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM7818M		
Make & Model:	NISSAN ALMERA, 1.5 4AT ABS AIRBAG 2WD 4DR (A)	Engine No:	HR15977556C
Reg. Date:	19/12/2014 (Man. Year: 2014)	Chassis No:	MNTBBAN17Z0004073
Colour:	Metallic Silver	Odometer:	141765 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	280.00	1,020.00	78.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,300.00	280.00	1,020.00	78.46
+ GST 7.00/7.00% (S\$)	91.00	19.60	71.40	78.46
Nett Amount (S\$)	1,391.00	299.60	1,091.40	78.46

INSPECTION

Date of Assignment:	11/04/2022		
Date Inspected:	13/04/2022	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	1.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2022)
Parts:	143	NISSAN ALMERA 1.5 4AT ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM7818M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	600.00	60.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	600.00	220.00
3	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			1,300.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >