

REPAIR DETAILS

Reference

Part Source:

Parts: N/A

(Last Synchronised: 18 Apr 2022)

Labour: Repairer's

SCANIA P410A4X2NZ 12.7 D (M) (Model not available in database)

Print Code: Woon Meng Motor Pte Ltd/XE6944B/18/04/2022 18:23

(Price denominated Standard List)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT TOP PANEL / <i>NT</i>			
2	1		*SCAN	0.00	0.00	*1,061.20 F
3	1		*IA / <i>me</i>	0.00	0.00	*55.10 F
4	1		*FRONT LOWER PANEL /	0.00	0.00	*55.10 F
5	1		*FRONT PANEL SIDE GRILLE O/S /	0.00	0.00	*839.40 F
6	1		*FRONT PANEL SIDE GRILLE N/S / <i>sel</i>	0.00	0.00	*91.10 F
7	1		*FRONT PANEL CENTER LOWER GRILLE /	0.00	0.00	*91.10 F
8	1		*XT	0.00	0.00	*196.70 F
9	1		*P410 / <i>me</i>	0.00	0.00	*77.10 F
10	1		*FRONT PANEL CENTER GRILLE LH / <i>le</i>	0.00	0.00	*75.50 F
11	1		*EMBLEM / <i>me</i>	0.00	0.00	*58.80 F
12	1		*AIR CON FILTER OUTER HOUSING ? - <i>era</i>	0.00	0.00	*75.30 F
13	1		*AIR CON FILTER INNER HOUSING ? - <i>era</i>	0.00	0.00	*141.10 F
14	1		*AIR CON FILTER ? - <i>de</i>	0.00	0.00	*480.40 F
15	1		*FRONT PANEL INNER FRAME ? - <i>bt</i>	0.00	0.00	*71.10 F
16	1		*FRONT PANEL HINGE N/S ?	0.00	0.00	*2,218.40 F
17	1		*FRONT PANEL HINGE O/S ?	0.00	0.00	*371.70 F
18	1		*FRONT PANEL LOCK / <i>BT</i>	0.00	0.00	*371.70 F
19	1		*FRONT PANEL LOCK BRACKET / <i>BT</i>	0.00	0.00	*248.30 F
20	1		*FRONT PANEL ABSORBER ?	0.00	0.00	*28.70 F
21	1		*FRONT PANEL INNER TOP SIDE GARNISH N/S ? - <i>dis</i>	0.00	0.00	*156.70 F
22	1		*FRONT PANEL LOWER CENTER GRILLE ? - <i>dis</i>	0.00	0.00	*36.40 F
23	1		*FRONT WIPER CENTER PANEL ?	0.00	0.00	*193.30 F
24	2		*FRONT WIPER SIDE PANEL ?	0.00	0.00	*1,246.40 F
25	2		*FRONT WIPER HANDLE ?	0.00	0.00	
26	1		*FRONT WIPER LINKAGE ?	0.00	0.00	
27	2		*FRONT WIPER BLADE ?	0.00	0.00	*636.90 F
28	2		*FRONT WIPER ARM ?	0.00	0.00	*107.40 F
29	1		*FRONT CORNER PANEL N/S / <i>BT</i>	0.00	0.00	*567.20 F
30	1		*FRONT CORNER PANEL INNER BRACKET N/S ? - <i>bt</i>	0.00	0.00	*677.10 F
31	1		*FRONT CORNER PANEL RUBBER N/S ? - <i>out</i>	0.00	0.00	*68.40 F
32	1		*FRONT HEADLAMP N/S / <i>N/S</i>	0.00	0.00	*733.20 F
33	1		*FRONT HEADLAMP TOP GARNISH N/S /	0.00	0.00	*1,342.40 F
34	1		*FRONT HEADLAMP GRILLE N/S / <i>N/S</i>	0.00	0.00	*26.40 F
35	1		*FRONT HEADLAMP GRILLE SIDE COVER N/S / <i>N/S</i>	0.00	0.00	*128.80 F
36	1		*FRONT HEADLAMP MEAT N/S ? - <i>dis</i>	0.00	0.00	*16.60 F
37	4		*FRONT BUMPER TOP STOPPER ? - <i>out</i>	0.00	0.00	*202.60 F
38	3		*FRONT BUMPER TOWING COVER ? - <i>dis</i>	0.00	0.00	*70.40 F
39	1		*FRONT BUMPER LOWER PANEL N/S ?	0.00	0.00	*25.20 F
40	1		*FRONT BUMPER / <i>M</i>	0.00	0.00	
41	2		*FRONT BUMPER BRACKET ? - <i>bt</i>	0.00	0.00	*3,254.10 F
42	1		*FRONT BUMPER FOG LAMP COVER N/S / <i>le</i>	0.00	0.00	*921.80 F
43	1		*FRONT BUMPER CENTER HANDLE ? - <i>dis</i>	0.00	0.00	*28.60 F
44	1		*FRONT BUMPER GRILLE ?	0.00	0.00	*885.10 F
45	1		*FRONT BUMPER GRILLE PANEL ?	0.00	0.00	
46	1		*FRONT BUMPER GRILLE PANEL OUTER GARNISH ?	0.00	0.00	
47	1		*FRONT BUMPER GRILLE PANEL SIDE GARNISH N/S ? - <i>dis</i>	0.00	0.00	*51.00 F

48	1	*FRONT CROSSMEMBER	?	bt	0.00	0.00	*2,791.00 F
49	1	*FRONT BUMPER SIDE GARNISH N/S	?	cut	0.00	0.00	*89.40 F
50	1	*FRONT STEP INNER PANEL N/S	?		0.00	0.00	*186.50 F
51	1	*FRONT STEP BRACKET N/S	?		0.00	0.00	*379.10 F
52	1	*FRONT STEP PANEL N/S	?		0.00	0.00	*501.40 F
53	1	*FRONT DOOR N/S	BT		0.00	0.00	*3,434.00 F
54	1	*FRONT DOOR LOWER HINGE N/S	?	bt	0.00	0.00	*140.10 F
55	1	*FRONT WHEEL TOP GARNISH N/S	?	del	0.00	0.00	*178.10 F
56	1	*FRONT MUDGUARD TOP GARNISH N/S	?		0.00	0.00	
57	1	*FRONT MUDGUARD INNER LOWER GARNISH N/S	?		0.00	0.00	*599.50 F
58	1	*WIRE HARNESS INNER HOUSING N/S	?		0.00	0.00	*172.50 F
59	1	*WIRE HARNESS OUTER HOUSING N/S	?		0.00	0.00	*92.70 F
60	1	*FRONT BUMPER SIDE GARNISH INNER BRACKET N/S	?	bt	0.00	0.00	*88.10 F
61	1	*FRONT DOOR CHEK N/S	?	bt	0.00	0.00	*68.40 F
62	1	*FRONT MUDGUARD FRONT INNER GARNISH BRACKET N/S	?	bt	0.00	0.00	*347.10 F
63	1	*REAR SIDE MUDGUARD N/S	?	del	0.00	0.00	*1,420.20 F
64	1	*REAR PANEL	?	bt	0.00	0.00	*1,840.10 F
65	1	*FRONT RADIATOR ASSY	BT		0.00	0.00	*2,313.70 F
66	1	*SPARE TANK	?		0.00	0.00	*723.00 F
67	1	*AIR CON CONDENSOR	BT		0.00	0.00	*1,635.20 F
68	1	*INTER COOLER	?	cut	0.00	0.00	*2,946.60 F
69	2	*SPARE TANK HOSE	?	bt	0.00	0.00	*161.20 F
70	1	*INTER COOLER BRACKET N/S	?	bt	0.00	0.00	*322.20 F
71	1	*RADIATOR FAN COWLING	?	crack	0.00	0.00	*458.20 F
72	1	*FAN BLADE	?		0.00	0.00	*2,621.10 F
73	1	*INTER COOLER HOSE	?		0.00	0.00	*236.70 F
74	1	*FRONT INNER PANEL PLATE	?		0.00	0.00	*130.20 F
75	1	*FRONT CABIN PUMP COVER	?		0.00	0.00	
76	1	*FRONT CABIN PUMP	?		0.00	0.00	*1,388.90 F
77	1	*AIR CON HOSE EXIT COMPRESSOR	?		0.00	0.00	*591.20 F
78	1	*AIR CON HOSE EXIT COMPRESSOR	?		0.00	0.00	*591.20 F
79	1	*FRONT CABIN PUMP BRACKET	?		0.00	0.00	*658.30 F
80	1	*FRONT CABIN ABSORBER BRACKET N/S - LONG	?	bt	0.00	0.00	*505.70 F
81	1	*FRONT CABIN ABSORBER BRACKET N/S - SHORT	?	bt	0.00	0.00	*409.60 F
82	1	*FRONT CABIN ABSORBER N/S	?	bt	0.00	0.00	*526.70 F
83	1	*FRONT CABIN TOP BRACKET N/S	?	bt	0.00	0.00	*219.50 F
84	1	*FRONT CROSSMEMBER	?		0.00	0.00	*2,433.50 F
85	1	*FRONT CABIN LOWER BRACKET N/S	?	bt	0.00	0.00	*1,001.50 F
86	1	*AIR CON HOSE EXIT CONDENSOR	?		0.00	0.00	*396.80 F
87	1	*OIL FILTER PIPE	?		0.00	0.00	*258.10 F
88	1	*OIL FILTER PIPE CAP	?		0.00	0.00	*34.00 F
89	1	*WIPER TANK HOSE	?		0.00	0.00	*37.10 F
90	1	*WIPER TANK	?		0.00	0.00	*187.90 F
91	1	*AIR DRYER	?		0.00	0.00	*5,009.40 F
92	1	*AIR HOSE	?		0.00	0.00	*17.60 F
93	1	*AIR HOSE	?		0.00	0.00	*34.70 F
94	1	*AIR DRYER TOP HOLDER	?	bt	0.00	0.00	*51.00 F
95	1	*FRONT HEADLAMP SIDE BRACKET N/S	?	bt	0.00	0.00	*154.40 F
96	1	*FRONT HEADLAMP LOWER BRACKET N/S	?	bt	0.00	0.00	*83.90 F
97	1	*AIR PIPE BRACKET N/S	?		0.00	0.00	*39.40 F
98	1	*AIR DRYER BRACKET (REAR)	?		0.00	0.00	*122.40 F
99	1	*WIPER HOSE	?		0.00	0.00	*25.40 F
100	1	*HEXAGON SCREW	?		0.00	0.00	*32.80 F
101	2	*FLANGE SCREW	?		0.00	0.00	*4.80 F
102	1	*FLANGE SCREW	?		0.00	0.00	*15.40 F
103	4	*CAPTIVE WASHER SCREW	?		0.00	0.00	*36.40 F
104	1	*HVAC	?	crack	0.00	0.00	*2,852.70 F
105	1	*AIR CON WIRE COVER	?		0.00	0.00	*30.00 F
106	2	*AIR CON SIDE BRACKET	?		0.00	0.00	*405.20 F
107	1	*FRONT DASHBOARD INNER REFORCEMENT	?		0.00	0.00	*1,346.10 F
108	1	*CHASSIS BRACKET N/S	?		0.00	0.00	*3,062.60 F

109	1	*FRONT DASHBOARD WIRE CASING	0.00	0.00	*16.20 F
110	1	*FRONT SIDE MIRROR COMPLETE N/S	0.00	0.00	*2,080.00 F
111	1	*AIR CON COMPRESSOR	0.00	0.00	*2,405.20 F
112	1	*FRONT WINDSCREEN GLASS	0.00	0.00	*888.00 F

F=Franchise part

Sub Total (S\$) 69,614.50
+ Margin on L,N Items 10.00% (S\$) 6,961.45

Total Parts (S\$) 76,575.95

Woon Meng Motor Pte Ltd/XE6944B/18/04/2022 18:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

proof

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	COOLANT	-
2	1	FRONT ERP BRACKET	15.00
3	1	FRONT WINDSCREEN SEALANT	80.00
Sub Total (\$\$)			95.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO PUTTY & SPRAY PAINTING	New	120 1,400.00
Labour Items			
2	TOWING FEE	New	150.00
3	TO REMOVE, REPLACE, REPAIR, INSTALL & WELD DAMAGED PARTS	New	4500 4,800.00
4	TO R & R AIR CON SYSTEM. TOP REFILL & TOP UP AIR CON GAS	New	280 480.00
5	TO R & R FRONT DASHBOSRD	New	250 450.00
6	TO R & R WIRE HARNESS	New	250 480.00
7	TO R & R DRIVER SEAT, PASSENGER SEAT, FLOOR CARPET AND ROOF TOP INNER TRIM	New	320 450.00
8	TO R & R FRONT CABIN	New	1000 1,200.00
9	TO R & R AIR PIPE	New	150 250.00
10	TO R & R FRONT WINDSCREEN GLASS	New	350 380.00
11	TO R & R FRONT RADIATOR & INTER COOLER	New	250 350.00
Gross Labour Cost (\$\$)			10,390.00

Woon Meng Motor Pte Ltd/XE6944B/18/04/2022 18:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

30 Days.

P/P

before part photos.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: