

(06/11/19)

ASS. REC. BY:

Thuvan

REF: nfac NS/INC22003331/Vty3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. MT/1168188-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC83114 Yr Regn: S/12 119

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Toyota prius hybrid c.c 1798

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 291377 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU903089046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 9/4/22 D.O.I. 11/4/22 1615

Survey held at CDGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA provided

LUMP SUM \$1300, 2DAYS

RED: 2171.1;62%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Date/Time: 11.04.2022 10:35

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4194804

JC NO:305511877

STOMER

REGN NO:

SHC8344U

MILEAGE

V/MS COMFORT TRANSPORTATION PTE LTD

MAKE:

TOYOTA

FUEL

STOMER NO 7010045

E.....1/2.....F

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

MODEL

PRIUS HYBRID(G4A11.04.2022 08:25

(R) 65508755

(O)

YR OF MANU

05.12.2019

TARGET DATE

(P)

CHASSIS CODE

JTDKB3FU903089046

COMPLETION DATE/TIME:


SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 09.04.2022

NATURE: 3P 09.04.2022

S/NO LABOR CODE DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

Exit Pass

2:

Vehicle No.:

3:

SHC8344U

le No.:

SHC8344U

CHLANG

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8344U

DATE 09.04.2022

MAKE/REG 05.12.2019

CHIANG/NTUC

MODEL TOYOTA PRIUS G4A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$503.04
1	REAR BUMPER LOWER COVER			\$654.96
1	REAR BUMPER REINFORCEMENT			\$378.32
1	REAR CENTRE UNDER COVER			\$425.25
1	REAR BUMPER REFLECTOR RH			\$55.00
1	REAR BUMPER TOW COVER			\$82.70
1	REAR TRUNK LOGO PRIUS			\$52.90
1	REAR TRUNK LOGO HYBRID			\$52.40
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40
10	REAR BUMPER CLIP		\$2.20	\$22.00
	SUB TOTAL			\$2,451.97
	25.00%			\$612.99
	DISCOUNTED TOTAL			\$1,838.97
1	BOOTLID COMFORT & TEL NUMBER			\$60.00
1	BOOTLID COMFORT APP			\$40.00
1	BUMPER REVERSE SENSOR			\$135.70
			\$0.10	\$212.13
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$600.00
	Check wiring and lighting			\$60.00
	Remove/Refix Reverse Sensor			\$60.00
	TOTAL LABOUR			\$1,420.00
	ESTIMATE TOTAL			\$3,471.10
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thuan

8223 5769

11/4/22 1615

L/s repair 2 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: