



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7751C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER-FR BUMPER	CUT	481.10	481.10
1	MOULDING-FRONT BUMPER CTR	SCRATCHED	368.50	368.50
1	GRILLE ASSY-RADIATOR	SERVICEABLE	1,568.80	-
1	LAMP ASSY-HEAD LH	SCRATCHED	2,110.30	2,110.30
1	CARRIER ASSY-FRONT END MO	CUT	949.30	949.30
1	BRACKET-FR BUMPER SIDE RH	NECESSARY	28.00	28.00
1	BRACKET-FR BUMPER SIDE LH	NECESSARY	28.00	28.00
10	BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	BEAM COMPLETE-FR BUMPER	BENT	1,136.70	1,136.70
1	DEP UNIT ASSY-BSD LH	SERVICEABLE	1,837.10	-
1	FLAP ASSY-ACTIVE AIR UPR	SERVICEABLE	824.60	-
1	PANEL ASSY HOOD	DENTED	2,253.80	2,253.80
1	HINGE ASSY HOOD LH	DEFORMED	118.70	118.70
1	HINGE ASSY HOOD RH	DEFORMED	118.70	118.70
1	LATCH ASSY-HOOD	DEFORMED	127.30	127.30
1	MOULDING-FRONT BUMPER LH	SCRATCHED	186.90	186.90
1	LAMP ASSY-DAY RUNNING LIG	CRACKED	642.50	642.50
1	PANEL-FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	EMBLEM-BLUE DRIVE LH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-2,683.54	-1,719.68
			10,734.16	6,878.72
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF PANEL-FENDER LH.		1,200.00	1,050.00
	SPRAY PAINT CHARGE.		800.00	750.00
	CHECK ALL LIGHTING.		50.00	30.00
	TO VAC. & TOP UP A/C GAS.		120.00	60.00
	TUFF COAT ON AFFECTED PARTS.		60.00	30.00

Report Ref No. NS/INC22003332/Vqy3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEE.		60.00	-
			2,290.00	1,920.00
GRAND TOTAL			13,024.16	8,798.72
RECOMMENDED COST OF REPAIRS (CONFIRMED)				8,798.72

Report Ref No. NS/INC22003332/Vqy3e2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.