

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0288/2022/JT  
**DATE** : 11-Apr-22  
**WIP** : 19360

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 13/4/22**

**YOUR INSURED VEH NO : EF 6969 A**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

**78 SHENTON WAY**

**#07-16 AIG BUILDING**

**SINGAPORE 079120**

**Attn: Motor Claims Dept**

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR SIA CHOON KIM (XIA CHUN IM)  
**ADDRESS** : 12B HOUGANG ST 11  
#10-62 THE MINTON  
SINGAPORE 534073  
**TELEPHONE** : HP +65 97904874  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 1900167053-01  
**VEHICLE NO** : SMP 5130 L  
**MODEL CODE** : AUDI A4 SEDAN 2.0 TFSI 8W  
**MODEL YEAR** : 28/9/2019  
**ENGINE NO** : CVK 086288  
**CHASSIS NO** : WAUZZZF44KA104996  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 11-Apr-22  
**PLACE OF ACCIDENT** : THE MINTON BASEMENT CAR PARK

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display original parts during resurvey
- Parts prices are subject to resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5130 L**

| S/N                         | NATURE OF JOBS                                                                                                                                   | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ 480.00        | / ✓                        |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                            | S/N \$ 350.00        | X NN                       |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.   | \$ 2,100.00          | 500 ✓                      |
| 4                           | TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.                                                                                                    | \$ 2,000.00          | 1100 ✓                     |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                   | S/N \$ 192.00        | / ✓                        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | <b>: \$ 5,122.00</b> |                            |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5130 L

|                              |                                                        |     | DAMAGED PARTS & PRICES |          |
|------------------------------|--------------------------------------------------------|-----|------------------------|----------|
| S/N                          | PARTS DESCRIPTION                                      | QTY | S/NETT                 | REMARKS  |
| 1                            | FRONT BUMPER <i>Re</i>                                 | 1   | \$ 2,377.00            | 1,901.60 |
| 2                            | FRONT BUMPER FIXING PARTS <i>X</i>                     | 1   | \$ 612.00              |          |
| 3                            | FRONT BUMPER SECURING STRIP <i>X</i>                   | 1   | \$ 79.00               |          |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>   | 1   | \$ 254.00              |          |
| 5                            | FRONT BUMPER AIR GUIDE - RH <i>X</i>                   | 1   | \$ 72.00               |          |
| 6                            | FRONT BUMPER AIR GUIDE GRILLE - RH <i>X</i> <i>cut</i> | 1   | \$ 151.00              | 120.40   |
| 7                            | FRONT BUMPER GUIDE SECTION - RH <i>X</i> <i>NN</i>     | 1   | \$ 41.00               |          |
| 8                            | FRONT BUMPER TOP COVER <i>X</i>                        | 1   | \$ 143.00              |          |
| 9                            | "CAUTION" STICKER <i>X</i>                             | 1   | \$ 16.00               |          |
| 10                           | AIR COND STICKER <i>X</i>                              | 1   | \$ 9.00                |          |
| 11                           | FRONT FENDER - RH <i>X</i>                             | 1   | \$ 861.00              |          |
| 12                           | FRONT FENDER ATTACHMENT PARTS <i>X</i>                 | 1   | \$ 211.00              |          |
| 13                           | FRONT FENDER CLOSING ELEMENT - RH <i>X</i>             | 1   | \$ 81.00               |          |
| 14                           | FRONT FENDER BRACKET - RH <i>X</i>                     | 1   | \$ 41.00               |          |
| 15                           | FRONT FENDER POP RIVET <i>X</i>                        | 6   | \$ 23.00               |          |
| 16                           | FRONT FENDER BRACE - RH <i>X</i>                       | 1   | \$ 132.00              |          |
| 17                           | FRONT FENDER BRACKET CENTER - RH <i>X</i>              | 1   | \$ 55.00               |          |
| 18                           | FRONT WHEEL HOUSING LINER - RH <i>X</i>                | 1   | \$ 262.00              |          |
| 19                           | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>    | 1   | \$ 149.00              |          |
| 20                           | FRONT WHEEL SPOILER - RH <i>X</i>                      | 1   | \$ 82.00               |          |
| <b>SUB TOTAL SPARE PARTS</b> |                                                        | :   | <b>\$ 5,651.00</b>     |          |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5130 L**

| S/N                         | PARTS DESCRIPTION                   | QTY | DAMAGED PARTS & PRICES |                  | REMARKS |
|-----------------------------|-------------------------------------|-----|------------------------|------------------|---------|
|                             |                                     |     | S/NETT                 |                  |         |
| 21                          | FRONT WHEEL SPOILER LOWER - RH      | 1   | \$                     | 40.00            | X {nn   |
| 22                          | FRONT FENDER LEDGE COVER LONG - RH  | 1   | \$                     | 35.00            | X       |
| 23                          | FRONT FENDER LEDGE COVER SHORT - RH | 1   | \$                     | 26.00            | X NN    |
| 24                          | HEADLIGHT - RH                      | 1   | \$                     | 8,294.00         | X       |
| 25                          | LIFT CYLINDER - RH                  | 1   | \$                     | 231.00           | X       |
| 26                          | LIFT CYLINDER CORRUGATED PIPE       | 1   | \$                     | 107.00           | X       |
| 27                          | SUNDRIES                            |     | \$                     | 300.00           | X NN    |
| <b>TOTAL SPARE PARTS</b>    |                                     | :   | \$                     | <b>12,158.00</b> |         |
| <b>TOTAL LABOUR CHARGES</b> |                                     | :   | \$                     | <b>5,122.00</b>  |         |
| <b>GRAND TOTAL</b>          |                                     | :   | \$                     | <b>17,280.00</b> |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

:  
:  
:  
:  
:  
:

*Eng Kai ap*  
*13/4/22*  
*before paint photos.*

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

*4 Days.*

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT