

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0288/2022/JT
DATE : 11-Apr-22
WIP : 19360

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 13/4/22

YOUR INSURED VEH NO : EF 6969 A

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SIA CHOON KIM (XIA CHUNJIN)
ADDRESS : 12B HOUGANG ST 11
#10-62 THE MINTON
SINGAPORE 534073
TELEPHONE : HP +65 97904874
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900167053-01
VEHICLE NO : **SMP 5130 L**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 28/9/2019
ENGINE NO : CVK 086288
CHASSIS NO : WAUZZZF44KA104996
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Apr-22
PLACE OF ACCIDENT : THE MINTON BASEMENT CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 5130 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,122.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5130 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	TBC	
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 79.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 254.00	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	
8	FRONT BUMPER TOP COVER	1	\$ 143.00	
9	"CAUTION" STICKER	1	\$ 16.00	
10	AIR COND STICKER	1	\$ 9.00	
11	FRONT FENDER - RH	1	\$ 861.00	
12	FRONT FENDER ATTACHMENT PARTS	1	\$ 211.00	
13	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	
14	FRONT FENDER BRACKET - RH	1	\$ 41.00	
15	FRONT FENDER POP RIVET	6	\$ 23.00	
16	FRONT FENDER BRACE - RH	1	\$ 132.00	
17	FRONT FENDER BRACKET CENTER - RH	1	\$ 55.00	
18	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	TBC	
20	FRONT WHEEL SPOILER - RH	1	\$ 82.00	
SUB TOTAL SPARE PARTS		:	\$ 3,125.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5130 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL SPOILER LOWER - RH	1	\$ 40.00	
22	FRONT FENDER LEDGE COVER LONG - RH	1	\$ 35.00	
23	FRONT FENDER LEDGE COVER SHORT - RH	1	\$ 26.00	
24	HEADLIGHT - RH	1	\$ 8,294.00	
25	LIFT CYLINDER - RH	1	\$ 231.00	
26	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00	
27	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 12,158.00	
TOTAL LABOUR CHARGES			\$ 5,122.00	
GRAND TOTAL			\$ 17,280.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT