



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM22003349/Kpa3q2 Date: 20/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9909C	Veh. Inspected	SND 4488M	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M03Y6N	Excess (\$)	0.00	
Assign From		Assign Date	11/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1332	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	W1K1183842N271224	Colour	METALLIC LIGHT BROWN	
Odometer	2585 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	HANKOOK	9 mm	
L/H Front Tyre	225/45 R18	HANKOOK	9 mm	
R/H Rear Tyre	225/45 R18	HANKOOK	9 mm	
L/H Rear Tyre	225/45 R18	HANKOOK	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/03/2022	Inspection Date	12/04/2022	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	