

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

M/S AIG

ESTIMATE REPAIR COST FOR GBC4246S

S/N QTY DESCRIPTION

		SUPPLY & REPLACE DAMAGE PORTION SS	S. Netf
1	1	FRAME, DRIVER SIDE VERTICAL 3/5-	\$ Dis 580.00 ✓
2	1	REAR DOOR RIGHT BOTTOM HINGE	\$ Sub 200.00 150
3	1	GRP BOARD 3/5.	\$ Cne 1,000.00 400
4	1	SUPPLY ADHESIVE TO FIX THE ABOVE	\$ 11 180.00 X
		ARGON WELDING AT JOINT OF STAINLESS STEEL DOOR	
5	1	FRAME & TO DISMANTLE & REPLACE WITH THE ABOVE ITEM	\$ 1,800.00 1600
6	1 pc	REAR TAILLAMP (216.20 LESS 25%)	a/c \$ Rye 172.96 X
			<u>\$ 3,932.96</u>

Not Authorized
LH
P/P 82730
5 days.
13/4/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: