

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305511878

Date : 14/04/22

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr Thevan

09/04/2022

Vehicle Reg No. : SHA7935G

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- GBF5930C
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges \$0.00
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable) 20%
 - Total for Lumpsum repair cost after Less:** \$1,150.00
 - Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Ms. Loke YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : Thevan

Date : 21/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2022)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA7935G/11/04/2022 11:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	*459.40 FLXr
2	1		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FLXr
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	*451.25 FLXr
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FLXr
5	1		*ANTENNA SMARTKEY	20.00	0.00	*40.50 FLXr
6	1		*REAR BUMPER FOG LAMP	20.00	0.00	*201.50 FLXr
7	1		*LICENCE LAMP	20.00	0.00	*85.30 FLXr
8	1		*REAR BUMPER TOWING COVER	20.00	0.00	*98.80 FLXr
9	1		*REAR BUMPER LWR CENTRE MOULDING ASSY	20.00	0.00	*155.00 FLXr
10	1		*REAR BUMPER RUBBER MAT	0.00	0.00	*50.00 FLXr
11	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	*55.00 F/cra
12	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*180.00 F/cra

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,193.55
- List Item Discount on L Items (S\$)	381.71
Total Parts (S\$)	1,811.84

ComfortDelGro Engineering Pte Ltd/SHA7935G/11/04/2022 11:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING
 2 SPRAY PAINTING CHARGE
 3 CHECK ALL LIGHTING
 4 REMOVE/REFIX REVERSE SENSOR

New

400.00 350

New

300.00 280

New

60.00 30

New

80.00 30

Gross Labour Cost (S\$)

840.00

ComfortDelGro Engineering Pte Ltd/SHA7935G/11/04/2022 11:23. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan

82235769

12/4/22 17/5

P/p repair 2 delays up

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: