



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-----------------|---------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 | | | Ref: CS/CTI22003365/y3 Date: 12/04/2022 Code: CTI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | YP 1341D | Veh. Inspected | SKD 7787R | |
| Policy No. | DMCVSAW000017012201 | Coverage (\$) | 0.00 | |
| Claim No. | SNM22D202166/C02 | Excess (\$) | 0.00 | |
| Assign From | ADELINE CHNG | Assign Date | 12/04/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 26/03/2022 | Inspection Date | | |
| Survey held at | YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |