

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 22 Jun 2022

Preliminary Advice

Insured : YP1341D

Vehicle No

TP Vehicle : SKD7787R
No

Accident Date : 26/03/2022

Make : MAZDA CX-5

Assignment Date : 12/04/2022

Date of : 24/05/2022

Est. Duration of : 3
Repair

Inspection

Inspection At : YEE AUTO PTE LTD (HQ)

160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY
SINGAPORE 575722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 9,801.00

Revised Amount :S\$ 3,512.48

Check Items (Estimated) :S\$ 0.00

Total :S\$ 3,512.48

Lump Sum Repair :S\$ 2,800.00

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.