

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22003368/AGNY3E2
Date: 15/08/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29150567MCX
Claimant Vehicle No : SMG2522G **Insured Vehicle No :** SLB5343A
Date of Loss: 09/04/2022 Nature of Claim: TP Claim No: 640998

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG2522G**
Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1439596
Reg. Date: 12/12/2018 (Man. Year: 2018) Chassis No: GK31332842
Colour: Grey Odometer: 54586 km
Engine Capacity: 1317 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,942.92	1,657.64	1,285.28	43.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	590.00	460.00	43.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,992.92	2,247.64	1,745.28	43.71
+ GST 7.00/7.00% (S\$)	279.50	157.33	122.17	43.71
Nett Amount (S\$)	4,272.42	2,404.97	1,867.45	43.71

INSPECTION

Date of Assignment: 12/04/2022
Date Inspected: 16/06/2022 Inspected At: Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717
Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2022)
Parts: 143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG2522G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE WEEKEND SEAL	Necessary	16.05 FL	*16.05 FL
2	1		*FRONT BUMPER	Deformed	529.60 FL	*529.60 FL
3	2		*FRONT BUMPER SIDE HOLDER - LH & RH	Not Necessary	56.80 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	285.50 FL	*- FL
5	1		*FRONT GRILLE	Cracked	395.40 FL	*395.40 FL
6	1		*FRONT GRILLE LOWER CHROME MOULDING	Cut	171.50 FL	*171.50 FL
7	1		*FRONT GRILLE TOP CHROME MOULDING	Not Necessary	292.30 FL	*- FL
8	1		*HEADLAMP - LH & RH	O/S Cracked	1,794.00 FL	*897.00 FL
9	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
10	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
11	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
12	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,651.15	2,059.55
- List Item Discount on L Items 20.00/20.00% (\$\$)	708.23	401.91
Total Parts (\$\$)	2,942.92	1,657.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	500.00	300.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	400.00	200.00
3	TO CHECK WIRING SYSTEM	New	50.00	30.00
4	TO SEND VEHICLE FOR WEEKEND SEAL INSPECTION	New	100.00	60.00
			Gross Labour Cost (\$)	590.00
			1,050.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >